

# MECCANO

(TRADE MARKS 296321, 501113, 76, 12633, 10274, 55/13476, 569/13, 884/25, 2913, 80, 124, 336, 18066, 5403, 41812, 4174, 9048, 5549, 2389, 91637, 83171, 157149, 32822, 200639, 209733, 214061, 214062, 12892, 29094, 33316, 1818, 16737, 18900, 72286, 494933-4-5-6, 139420, 383/13, 5848, 50294, 10/12258, 22826, 18982, 20063/925, 2189, 7315, 29041, 26877, 6595, 404718, 410379)

HORNBY'S ORIGINAL SYSTEM-FIRST PATENTED IN 1901

## INSTRUCTIONS

FOR OUTFITS

Nos. 00 to 3

Price 1/6

Copyright by MECCANO LIMITED, LIVERPOOL, throughout the world

No. 30A


ENGLISH EDITION

## MECCANO

## REAL ENGINEERING IN MINIATURE

The Meccano system is composed of over two hundred and fifty different parts, mostly made of steel or brass, each one of which has a specific mechanical purpose. These parts combine to form a complete miniature engineering system with which practically any mechanical movement may be reproduced in model form. More can be accomplished with Meccano than with any other constructional toy, for no other system has such possibilities. The genius is in the parts and you can commence to build models as soon as you get your Outfit home. A screw-driver, provided in the Outfit, is the only tool necessary.

There is no limit to the number of models that can be built with Meccano—Cranes, Clocks, Motor Cars, Ship-Coalers, Machine Tools, Locomotives—in fact everything that interests boys. The most wonderful feature about the system is that it is real engineering; it is fascinating and delightful and it gives you a satisfaction beyond anything that you have ever previously experienced.



#### HOW TO BUILD WITH MECCANO

Make the simple models first—there is loads of fun in them—and then try to improve them. Every model can be made in a dozen different ways. It is important to screw up all the nuts and bolts tightly to ensure that your models will be strong and firm when they are completed. When you have built all the models shown in this book you will want to build others of a more advanced type, and you cannot do better than purchase a copy of the No. 4-7 Manual from your dealer. This Manual contains illustrations of a fine selection of models, a large number of which you will be able to build by adding a few extra parts to your equipment.

Meccano is sold in ten different Outfits, numbered 000 to 7. All Meccano parts are of the same high quality and finish, but the larger Outfits contain a greater quantity and variety of parts, making possible the construction of more elaborate models. Each Outfit, except the No. 000, may be converted into the one next higher by the purchase of an Accessory Outfit (see page 125). Thus a No. 00 may be converted into a No. 0 by adding to it a No. 00A. A No. 0A then converts it into a No. 1 and so on up to No. 7. No matter with which Outfit you commence, you may build it up by degrees until you possess a No. 7. It is important to remember that Maccano parts may be bought separately at any time in any quantity.

All models shown in this Manual are numbered and for reference purposes each model number is preceded by the number of the Outfit with which it may be built. Thus, for example, model No. 00.60 may be built with No. 00 Outfit, and model No. 2.20 with No. 2 Outfit.

#### MECCANO SERVICE

The service of Meccano does not end with selling an Outfit and an Instruction Manual. When you want to know something more about engineering than is now shown in our books, or when you strike a tough problem of any kind, write to us. We receive over 200 letters from boys every day all the year round. Some write to us because they are in difficulty, others because they want advice on their work or pleasures, or about the choice of a career. Others, again, write to us just because they like to do so and we are glad to know that they regard us as their friends.

Although all kinds of queries are put to us on all manner of subjects, the main interest is, of course, engineering. No one has such a wonderful knowledge of engineering matters as that possessed by our staff of experts. This vast store of knowledge, gained only by many years of hard-earned experience, is at your service. We want the Meccano boy of to-day to be the famous engineer of to-morrow.



#### THE "MECCANO MAGAZINE"


The Meccano Magazine is the Meccano boy's own newspaper. It tells him of the latest Meccano models; what Meccano Clubs are doing; how to correspond with other Meccano boys; the Competitions that are running, etc. It contains splendid articles on such subjects as Railways, Famous Engineers and Inventors, Electricity, Bridges, Cranes, Wonderful Machinery, Aeronautics, Latest Patents, Radio, Stamps, Photography, Books and other topics of interest to boys, including suggestions from Meccano boys for new Meccano parts and correspondence columns in which the Editor replies to his readers' enquiries. The Magazine is published on the first of each month. Write to the Editor, Meccano Magazine, Old Swan, Liverpool, enclosing 6d. in stamps, and giving the names and addresses of three of your chums who are not Meccano boys. He will then forward a specimen copy of the "M.M." post free. If you wish to become a regular subscriber the rates are 4/- for six issues or 8/- for twelve issues, post free. If you prefer to do so, you may order the Magazine from your Meccano dealer or from any newsagent or bookstall, price 6d.

#### MECCANO STANDARD MECHANISMS

There are many Meccano movements that have to a certain extent become standardised; that is to say they may be applied to more than one model, in most cases without any alteration, but in some few instances with only slight alterations to the original movement. These have been collected and classified, and may be obtained in the form of a Manual entitled "Meccano Standard Mechanisms." This Manual describes in detail various belt and rope mechanisms, roller and ball bearings, screw mechanisms, gear boxes and gear ratios, etc. Every Meccano experimenter has need of this useful book.



You may obtain a copy of the "Standard Mechanisms" Manual from your dealer, price 1/-, or direct from Meccano Ltd., Old Swan, Liverpool, price 1/1½ post free.



S.M. 262

#### SIMPLE MECCANO PIVOTS

In building Meccano models it is frequently required to attach two parts together so that one or both are quite free to swivel. A very simple way to do this is shown under detail number 262 in the "Meccano Standard Mechanisms" Manual, and for the benefit of those readers who are unable to consult the special Manual, we have reproduced this detail. As will be seen, it consists of a simple type of pivot or swivel bearing formed by a bolt and two nuts. The bolt is secured rigidly to a Strip or Plate, etc., by means of the nuts, which are secured tightly against opposite sides of the Strip, sufficient space being left beneath the head of the bolt to permit another Strip to turn freely about its shank.


A somewhat similar form of swivel-joint, also widely used, consists of a bolt and lock-nuts (Standard Mechanism No. 263). The two Strips to be connected pivotally are placed on the bolt and held in position by two nuts locked together on the shank. The Strips must be allowed a certain amount of play so that they can pivot independently about the bolt. These pivoting devices will be found equally valuable in the simplest and the most elaborate models.


## STRIPS, GIRDERS AND BRACKETS رشی [00000000] WHEELS, GEARS, ETC. 30ª & 30º


## Particulars of Meccano Parts


Perforated Strips	No. 1 P. 1/2 F /20%
No. No.	37f. Nuts and Eolts, 7/32"
1. $12\frac{1}{2}''$ 1a. $9\frac{1}{2}''$ 2 3. $3\frac{1}{2}''$ 3 4. $3^{''}$	37g. " " " …
1a. 9½" 4 3"	38. Washers
1b. $7\frac{1}{2}''$ 5. $2\frac{1}{2}''$	40. Hanks of Cord
2. $5\frac{1}{2}''$ 6. $2''$	41. Propeller Blades
2a. $4\frac{1}{2}''$ 6a. $1\frac{1}{2}''$	43. Springs
Angle Cindora	44 Cranked Bent Strips
Angle Girders	45. Double " " $\frac{1}{2}$ "
7. $24\frac{1}{2}''$   9a. $4\frac{1}{2}''$	43. Double " " "
7a. $18\frac{1}{2}''$ 9b. $3\frac{1}{2}''$ 9c. $3''$	46. " Angle Strips, 2½" × 1"
8. 12½" 9c. 3"	47. " " $\frac{2\frac{1}{2}'' \times 1\frac{1}{2}''}{\dots}$
Q2 Q1"   Qd Q1"	47a. " " " $3'' \times 1\frac{1}{2}$ "
8b. 7½" 9e. 2"	48. " " $\frac{1}{2}'' \times \frac{1}{2}" \dots$
	48a. " " $2\frac{1}{2}'' \times \frac{1}{2}''$
	405 21" 1"
10. Flat Brackets	48c. " " " 4½"×½"
11. Double Brackets	48c. " " $\frac{4\frac{1}{2}'' \times \frac{1}{2}''}{5\frac{1}{2}'' \times \frac{1}{2}''}$
12. Angle Brackets, $\frac{1}{2}'' \times \frac{1}{2}''$ 12a. " " $\frac{1}{2}'' \times 1$ "	
12a. " " 1″×1″	50a. Eye Pieces, with boss
12b. " " $1'' \times 1''$	<ol> <li>Perforated Flanged Plates, 5½" × 2½"</li> </ol>
" Axle Rods	52a. Flat Plates, $5\frac{1}{2}'' \times 3\frac{1}{2}''$
13. 11½"   16a. 2½"	52a. Flat Plates, $5\frac{1}{2}'' \times 3\frac{1}{2}''$ 53. Perforated Flanged Plates, $3\frac{1}{2}'' \times 2\frac{1}{2}''$
13. $11\frac{1}{2}''$   16a. $2\frac{1}{2}''$ 16b. $3^{''}$	53a. Flat Plates, $4\frac{1}{2}'' \times 2\frac{1}{2}''$
13a. 8 <sup>#</sup> 16b. 3 <sup>#</sup> 14. 64 <sup>#</sup> 17 2 <sup>#</sup> 15. 5 <sup>#</sup> 18a. 14 <sup>#</sup>	54 Desferated Florand Contag Distag
14. $6\frac{1}{2}''$ 17 2"	54. Perforated Flanged Sector Plates
	55. " Strips, slotted, $5\frac{1}{2}$ " long
15a. 4½" 18b. 1"	55a. " " " 2" "
16. 3½"	56. Instruction Manual, "No. 4-7"
	2.32
19s. " Small	T 00
19s. "Small	
20. Flanged Wheels, 1½" diam	56c. Meccano Standard Mechanisms Manual
20. Flanged Wheels, 1 <sup>*</sup> / <sub>1</sub> ," diam	56d " Book of New Models
" Pulley Wheels	56f. Bound Manual
19b. 3" dia. with centre boss and set screw	57. Hooks
10 0#	57a. " Scientific
	57a. " Scientific 57b. " Loaded
20a. 2" " " " " " " " " 21. 1½" " " " " " " " " " " " " " " " " " "	58. Spring Cord
$21.  1\frac{1}{2}''$ , , , , , ,	50. Spring Cord
22. 1" ,, ,, ,, ,,	58a. Coupling Screws for Spring Cord
23a, ‡"	59. Collars with Set Screws
23a. ½" " " " " " "	59. Collars with Set Screws 61. Windmill Sails
23a. ½ " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails
23a. ½" "" "" "" "" "" "" "" "" "" "" "" ""	59. Collars with Set Screws 61. Windmill Sails 62. Cranks
23a. ½" "" "" "" "" "" "" "" "" "" "" "" ""	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks
23a. ½" "" "" "" "" "" "" "" "" "" "" "" ""	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 62b. Double Arm Cranks
23a. ½" "" "" "" "" "" "" "" "" "" "" "" ""	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings
23a. ½" ,, without ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63. Octagonal Couplings
23a. ½" ,, without ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings
23a. ½" ,, without ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings
23a. ½" ,, without ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings
23a. ½" , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 65c. Centre Forks
23a. ½" , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 65c. Centre Forks
23a. ½" , without , , , , , , , , , , , , , , , , , , ,	59.         Collars with Set Screws           61.         Windmill Sails           62.         Cranks           62a.         Threaded Cranks           62b.         Double Arm Cranks           63.         Couplings           63a.         Octagonal Couplings           63b.         Strip Couplings           63c.         Threaded Couplings           64.         "Bosses           65.         Centre Forks           66.         Weights, 50 grammes
23a. ½" , without , , , , , , , , , , , , , , , , , , ,	59.         Collars with Set Screws           61.         Windmill Sails           62.         Cranks           62a.         Threaded Cranks           62b.         Double Arm Cranks           63.         Couplings           63a.         Octagonal Couplings           63b.         Strip Couplings           63c.         Threaded Couplings           64.         "Bosses           65.         Centre Forks           66.         Weights, 50 grammes
23a. ½" , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews & "
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews & "
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews & "
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews & "
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews & "
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Octagonal Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64 80sses 65. Centre Forks 66. Weights, 50 grammes 67 70 set Screws 69a. Grub Screws, ½" 69b 77, 792" 70. Flat Plates, 5½" × 2½" 71 72 73 74 75 76 76 77 77 78 79 79 70 71 71 71 72 74 75 76 77 78 79 79 70 70 71 71 71 72 74 75 76 77 78 79 79 70 70 71 71 71 72 73 74 75 76 77 78 79 79 70 70 71 71 72 74 75 76 77 78 79 79 70 71 71 71 72 74 75 76 77 77 78 79 70
23a. ½ " " without " " " " " " 22a. ½ " " without " " " " " " " 23. ½ " " " " " " " " 24. Bush Wheels "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62. Threaded Cranks 63. Couplings 63. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25" 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "7/32" 70. Flat Plates, 5½ × 2½" 712. ", "2½ × 2½" 72. "
23a. ½ , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "7/32" 70. Flat Plates, 5½" 2½" 76. Triangular Plates, 2½" 77. "24" 77. "74"
23a. ½ " " without " " " " " " " 22a. ½" " without " " " " " " " " 23. ½" " " " " " " " " 25. Pinion Wheels, ¼ diam., ¼ wide 25a. " " ¾ " " ¾ " " ½ " " 26b. " " ¾ " " ¼ " " ¼ " " 26a. " " ¾ ¼ " " ¼ " " ¼ " " 26b. " " ¼ " " ¼ " " ¼ " " ½ " " ¼ " " 26b. " " ¼ " " ¼ " " ¼ " " ½ " " ¼ " " ½ " " ¼ " " ½ " " ½ " " ¼ " " ½ " ½ " ½ " " " " ½ " ½ " ½ " ½ " " ½ " " " ½ " ½ " ½ " ½ " ½ " ½ " ½ " ½ " " " ½ "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62. Threaded Cranks 62b. Double Arm Cranks 63. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25" 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "7/32" 70. Flat Plates, 5½ × 2½" 71. "1"
23a. ½ , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64 80sses 65. Centre Forks 66. Weights, 50 grammes 67 68. Woodscrews, ½ 69. Set Screws 69a. Grub Screws, 5/32" 69b 70. Flat Plates, 5½ × 2½" 71 72 72 74. **Z* **Z* **Z* **Z* **Z* **Z* **Z* **
23a. ½ , without , , , , , , , , , , , , , , , , , , ,	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64 80sses 65. Centre Forks 66. Weights, 50 grammes 67 68. Woodscrews, ½ 69. Set Screws 69a. Grub Screws, 5/32" 69b 70. Flat Plates, 5½ × 2½" 71 72 72 74. **Z* **Z* **Z* **Z* **Z* **Z* **Z* **
23a. ½ " " without " " " " " " 22a. ½" " without " " " " " " " " 23. ½" " " " " " " " 25. Pinion Wheels " " " " " " " 25. Pinion Wheels, ¼" diam., ¼ wice 25a. " " ¾ " " ¾ " " ¾ " " ½ " " 26b. " " ¾ ¼ " " ¾ " " ¼ " " 26a. " " ¾ ¼ " " ¾ " " ¼ " " 26b. " " ¾ ¼ " " ¾ " " ¾ " " 26b. " " ¼ ¼ " " ¾ " " ½ " " 3 ½ " " ¾ " " ½ " " 27b. 133 " " " ¾ " " ¾ " " 3 ½ " " 3 ½ " " ¾ " 3 ½	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64 80sses 65. Centre Forks 66. Weights, 50 grammes 67 68. Woodscrews, ½ 69. Set Screws 69a. Grub Screws, 5/32" 69b 70. Flat Plates, 5½ × 2½" 71 72 72 74. **Z* **Z* **Z* **Z* **Z* **Z* **Z* **
23a. ½ " " without " " " " " " " 22a. ½ " " without " " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. Bosses 65. Centre Forks 66. Weights, 50 grammes 67. 25 68. Woodscrews, ‡" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "7/32" 69b. "7/32" 70. Flat Plates, 5½ × 2½ 71. "2½ × 2½ 72. "2½ × 2½ 73. "17 74. "Screwed Rods 75. "80a. 3½" 79. 8° 80b. 4½" 799. 8° 80b. 4½"
23a. ½ " " without " " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails 622. Cranks 623. Threaded Cranks 624. Double Arm Cranks 633. Octagonal Couplings 634. Octagonal Couplings 635. Strip Couplings 636. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25" 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "7/32" 70. Flat Plates, 5½ × 2½ 72. "2½ × 2½ 74. "1" 77. "1" 77. "1" 78. Triangular Plates, ½½" 77. "Screwed Rods 78. 11½" 80a. 3½" 79a. 6" 81b. 2½" 79a. 6" 81b. 2½" 80b. 4½" 80c. 3½" 80c
23a. ½ " " without " " " " " " " 22a. ½" " without " " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "732" 70. Flat Plates, 5½" × 2½" 71. "25" 72. "2½" × 2½" 73. "1" 74. "1" 75. Screwed Rods 78. 11½" 79a. 6" 80. 5" 80a. 3½" 80b. 4½" 80b. 5" 80b. 4½" 80crewed Strips, 10" radius
23a. ½ " " without " " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Couplings 63a. Octagonal Couplings 63b. Strip Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5/32" 69b. "732" 70. Flat Plates, 5½" × 2½" 71. "25" 72. "2½" × 2½" 73. "1" 74. "1" 75. Screwed Rods 78. 11½" 79a. 6" 80. 5" 80a. 3½" 80b. 4½" 80b. 5" 80b. 4½" 80crewed Strips, 10" radius
23a. ½ " " without " " " " " " " 22a. ½" " without " " " " " " " " 23. ½" " " ½" " " 25. Pinion Wheels, ¾" diam., ¾ wice 25a. " " ¾" " ¾" " ¾" " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " " " ½ " " " " ½ " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " " ½ "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Octagonal Couplings 63a. Octagonal Couplings 63a. Octagonal Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5, 32" 69b. "7,32" 70. Flat Plaics, 5½"×2½" 71. "17. "2." 72. "2½"×2½" 73. "17. "5. "17. "5. "5. "7. "17. "5. "5. "5. "5. "5. "5. "5. "5. "5. "5
23a. ½ " " without " " " " " " " " " " " " " " " " " " "	59. Collars with Set Screws 61. Windmill Sails 622. Cranks 623. Threaded Cranks 624. Double Arm Cranks 625. Double Arm Cranks 633. Octagonal Couplings 634. Octagonal Couplings 635. Strip Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25" 68. Woodscrews, ½" 69. Set Screws 693. Grub Screws, 5/32" 694. "7/32" 70. Flat Plates, 5½" × 2½" 71. "1" 72. "2½" 72. "2½" × 2½" 73. "1" 74. "1" 75. Screwed Rods 794. 6"   \$04. 3½" 794. 6"   \$11. 2² 80. 5" Strip Curved Strips, 10" radius 895. 3" "curved Strips, 10" radius 896. 3" "radius, 4 to circle
23a. ½ " " without " " " " " " " 22a. ½" " without " " " " " " " " 23. ½" " " ½" " " 25. Pinion Wheels, ¾" diam., ¾ wice 25a. " " ¾" " ¾" " ¾" " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " " " ½ " " " " ½ " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " ½ " " " ½ " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " ½ " " " " " ½ "	59. Collars with Set Screws 61. Windmill Sails 62. Cranks 62a. Threaded Cranks 62b. Double Arm Cranks 63a. Octagonal Couplings 63a. Octagonal Couplings 63a. Octagonal Couplings 63c. Threaded Couplings 64. "Bosses 65. Centre Forks 66. Weights, 50 grammes 67. "25 68. Woodscrews, ½" 69. Set Screws 69a. Grub Screws, 5, 32" 69b. "7,32" 70. Flat Plaics, 5½"×2½" 71. "17. "2." 72. "2½"×2½" 73. "17. "5. "17. "5. "5. "7. "17. "5. "5. "5. "5. "5. "5. "5. "5. "5. "5


PLATES  76  53  RODS, CRANKS AND COUPLINGS
134 64 166 121 116 <sup>A</sup> 144 165
30   19 <sup>5</sup>   171   170
MISCELLANEOUS
151 152 153 153 162 138A 66&67 142A
41 57 122 578 157 156 169 149
106A 151 35 59 104
101 120 120A 158A 158A 158A 159 57A 94 105 65 115
163 34 <sup>B</sup> 114











































#### HOW TO CONTINUE


This completes our examples of models that may be made with MECCANO Outfit No. 00. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 00A Accessory Outfit, the price of which may be obtained from any Meccano dealer.






## Model No. 0.22

#### Model No. 0.23 Battleship



#### Model No. 0.19 Strong Man



Model No. 0.20 Aeroplane

Parts

required:

4 of No. 10



4	of	No.	2	8	of	No.	37 111c 125 126a
3	"	10	5	1	,,	,,	111c
2	,,	13	12	2	"	,,	125
1	1,	13	24	1	,,	13	126A

Model No. 0.24 Gymnast




		Par	ts	requi	red	:	
2	of	No.	2	1 1	of	No.	24
4	,,	. ,,	5	12	,,	,,	37
4	,,	,,,	10	1	,,	.,,	37A
1	,,	2.3	12	1	2.1	11	52
1	11	"	16	1	22	"	90A
2	,,	12	22	1	33	,,,	111c
1	,,	"	23	i			/-/


Parts required:

2 of No. 2


Model No. 0.25 Rocking Horse




Model No. 0.21 Cattle Truck




Parts required: " 111c




Model No. 0.26





#### Model No. 0.35 Tramway Car



#### Parts required:

3	of	No.	2	16	of I	۷o.	37
6	,,	"	5	6	,,	,,	37A
2	,,	"	10	2	"	,,	48A
2.	"	13	16	1	"	11	52
2	,,	,,	17	4	,,	,,	90a
4	,,	"	22	6	,,	,,	111c
6	,,	32	35	2	,,	,,	125

#### Model No. 0.36


## Motor Boat

	-	w.				Section 2019	
	art			4	•		<b>a</b> )
re	equ	ired:					
2	of	No.	2	1	of	No.	23
2	,,	,,	5	7	,,	,,	37
3	,,	,,	10	1	,,	,,	37A
1			11	1	,,	,,	111c

#### Model No. 0.37 Arm Chair




## Model No. 0.38 Torpedo Boat




## required:

-	1		
2	of	No.	2
2	,,	,,	5
3	,,	,,,	10
2	21	"	11
2	,,	,,	12
1	23	12	17
11	"		37
4	"	"	37A
D	,,	,,	111c

#### Model No. 0.40 Gramophone




#### Model No. 0.43 Prehistoric Armadillo




Model No. 0.44 Motor Cycle and Side Car

#### Model No. 0.39 Piano



#### Model No. 0.41 Milk Maid



#### Parts required:


1	of	No.	5	10	of	No.	
4	,,	,,	10	1	,,	**	37A
2	,,	,,	11	1	"	"	44
3	,,	,,	12	3	,,	**	90A
1	,,	,,	16	1	,,	"	111c
3	,,	,,	22	1	,,	1)	125
1	,,	,,	23	1	,,	12	126a


#### Model No. 0.42 Sword


Parts


Parts required: 4 of No. 2 | 10 of No. 37 | 3 of No. 90A















#### Model No. 0.70 The Missing Link


re	equi	red		
	o f	No.	5	
4	22	22	10	
8	,,	22	12	
1	23	2.3	24	
16	22	2.1	37	
6	,,	23	37A	
1	,,	22	52	3
4	,,	1)	90 A	A
6	,,	1)	111c	A



125 126A


#### Parts required:

1	of	No.	5	16	of	No.	37
1	27	21	10	1	22	21	37A
2	,,,	22	11	1	,,	21	52
7	37	21	12	4	2.3	12	90 A
1	,,,	22	22	2	1.7	12	111c
1	27	21	23	2	13	1)	126A



## Galvanometer

1	of	No.	12
1	2,1	"	17
5	1)	2.2	37
4	,,	,,	37 A
1	,,	2.5	40
1	,,	"	52
4	,,	,,	90 A
2	,,	11	1110



		1 di	10 10	, qu	1100	4 .		
7	of	No.	5	1	of	No.	37 A	
4	22	23	10	1	,,	1)	48A	
1	,,	21	12	1	**	11	52	
1	,,	22	23	4	,,	37	90 A	
13	,,	,,,	37	1	2.1		1110	
		1		1			126A	




3	of	No.	2	2	of	No.	37A
9	17	,,	5	1	21	11	40
1	,,,	12	16	1	,,	23	52
2	"	1)	22	2		23	111c
16	21	2.1	37	2	,,		126A


## Model No. 0.69 Coster's Barrow





Parta	required
1 di to	required


2	of	No.	5	13	of	No.	37
1	,,	23	11	1	23	do.	52
1	,,	23	17 24	4	23		90 A
1	,,	"	24	2	23	22	126A













#### Model No. 0.95 Trolley



#### Parts required:

2	of	No.	2	8	of	No.	37
2		*1		2	,,	**	48
4	,,	,,	22	1		*1	52
		4	of N	10.	90 A	A	

#### Model No. 0.96 Pen Rack




#### Model No. 0.97 Walking Man

Parts required:


5 of No. 5 3 ,, ,, 10 2 ,, ,, 12 1 ,, ,, 22 7 ,, ,, 37 3 ,, ,, 90

#### Model No. 0.98 Pump




The connecting Strip is pivoted by Bolts and Nuts at one end to the Bush Wheel and at the other end to the cross beam. The latter is pivoted by the same means to the upright.


#### Model No. 0.99 Aerial Ropeway



#### Model No. 0.100 Luggage Truck



## Model No. 0.101 Drafting Table




#### Model No. 0.102 Arm Chair

Parts required:


2 of No. 2
4 , 4, 5
12 , 37
1 , 48A
1 , 52
3 , 90A




#### Model No. 0.103 Rattle




#### Model No. 0.104 Shearing Machine



#### Model No. 0.105 Anchor






#### Model No. 0.106 Portal

		red	*.5
4	of	No.	2
2	23	,,	11
8	23	2.5	12
1	21	23	22
6	23	**	37
6	2.1	2.3	37A
2	27	,,	48 A
1	2.3	"	52
4	,,	,,	90 A
6	,,	,,	111c

#### Model No. 0.107 The Fencers

Parts required:

#### Model No. 0.108 Machine Gun



#### Parts required:


2	of	No.	11	1	of	No.	22
4	12	"	12	12	,,	. 13	37
1	,,	,,,	16	1	"	1)	52
1	,,	,,	19s	4	,,,	2)	90 A

#### Model No. 0.109 Single Sheave Pulley Block





Parts required:
2 of No. 5 | 7 of No. 37A
1 ,, 23 | 1 ,, 57c
3 of No. 111c

## Model No. 0.110 Tea Wagon




Parts required:







#### Model No. 0.125 Drilling Machine



#### Model No. 0.127 Scales



#### Model No. 0.129 Cot



#### Model No. 0.126 Counter Scales

Parte	required	

Parts	required:	
1 of No. 2 2 ,, 10 2 ,, 12 1 ,, 17	1 ,, ,, 44	

#### Parts required:

2	of	No.	2	2	of	No.	48A
9	,,	12	37	1	,,	"	52
1	11	"	37A	4	23.		90 A
1	12	**	40	1	**	12	126

Model No. 0.128 Single Sheave Pulley Block





## Parts

re	qui	red	
1	of	No.	23
12	,,	,,	37A
1	,,	23	57c
4	23	"	111c
2	319		126A


#### Model No. 0.130 Couch

#### Parts required:






#### Model No. 0.131 Rock Drill



#### Parts required:

1	of	No.	11 16 17 19s	4	of	No.	22	2	of	No.	48A
2	.,,	.,,	16	1	12	"	24	1	,,	,,	52
1	,,	,,	17	2	,,	"	35	2	32	,,	125
1	(55)	1000	19s	5			37				


#### Model No. 0.132 Well Windlass




#### Parts required:

6	of	No.	5 12 19s	2	of	No.	22	1	of	No.	40
4		1.0	12	1	2.1	12	24	1	,,,	1)	57c
1			19s	12	- 11	11	37	4	12	,,,	90A


#### Model No. 0.133 Prancing Horse





The Strip 1 forming part of the body is free to move about the Bolt 2, but two Nuts on the latter secure the rear legs and tail rigidly together. The arrangement of the various Strips about this Bolt 2 is shown more clearly in Fig. 0.133A. The Strip 3 is free to move at each end about pivots formed from Bolts and Nuts.





#### Model No. 0.135 Swivelling Crane











Model No. 0.141

Junction Signal

Parts required:

#### Model No. 0.138 Sled

Parts required:
6 of No. 37 | 1 of No. 52
1 ,, ,, 48a | 4 ,, ,, 90a


3	of	No.	2	1 1	of	No.	24
1	"	,,	11	16	,,	23	37
4	,,,	,,	12	2	23	27	37 a
1	"	23	15	2	1,1	12	48A
2	21	1)	16	1	"	23	52
4	11	12	22	4	"	21	90 a
		2	~ F N	0	1 1 1	~	


Parts required:


#### Parts required:

4	of	No.		1 1	of	No.	35
2	13	22	5	16	21	23	37
4	12	. ,,	10	6	21	23	37 A
1	11	,,,	11	2	23	13	48A
1	,,	21	16	1	12	12	52
1	"	,,,	17	2	,,	,,,	90 A
3	,,	23	22	6	1,	",	111c
1	,,	1)	24	1	12	,,,	125
		2 0	f N	0.	126	)	


#### Model No. 0.143 Bench Lathe







#### Model No. 0.146 Horizontal Engine




#### Model No. 0.148 Bath Chair

Model No. 0.147

Punching Machine

Parts


required: 3 of No. 2



#### Model No. 0.144 Bench


Parts required:

2 of No. 2 | 1 of No. 52 8 ,, 37 | 4 ,, 90A



required:


4 of No. 22 1 of No. 52



#### HOW TO CONTINUE

This completes our examples of models that may be made with MECCANO Outfit No. 0 (or No. 00 and No. 00A). The next models are a little more advanced, requiring extra parts to construct them. The necessary parts are all contained in a No. 0A Accessory Outfit, the price of which may be obtained from any Meccano dealer.

#### Model No. 1.1 Jockey Pulley




#### Parts required:

1	of	No.	3	2	of	No.	35	1	of	No.	52
4	"	23	5	20	,,	"	37 37a 48a	1	,,		54
2	"	,,	17	1	,,	,,	37a	2	,,	"	111c
4	,,	**	22	1	**	22	48A	2	,,	,,	126


The weight of the pivoted 3½" Strip, augmented by the 1" fast Pulley Wheel, causes the jockey pulley to press on the belt. Hence the latter is kept always taut.

#### Model No. 1.2 Triangle of Forces




The suspended weights represent three forces acting on a central point. If a triangle is drawn with its sides respectively parallel to the three converging cords, i.e., parallel to the directions of the three forces, the lengths of the sides will be found to be proportional to the respective magnitudes of the forces.

#### Model No. 1.5 Belt Gear Right-angle Drive Transmission




Model No. 1.3

Band Brake



Model No. 1.4
"H" Girder


Parts
required:
6 of No. 2
2 , , 10
8 , , 12
12 , 37




Model No. 1.6

Bacon Slicer
Parts required:

6	of	No.	5	2	of	No.	22
2	,,	,,	10	1	->>	,,	35
1	,,	,,	16	10	- 23	,,	37
1	"	"	19в	1	,,	,,	. 52
1	,,	17	19s	2	**	5. 15	125









The fulcrum is at one end, the load at the other and the power lies between the two.


#### Model No. 1.9 Compound Triangulated Truss



#### Model No. 1.10 Howe Truss







Model No. 1.12 45° Set-Square


Model No. 1.13
60°
Set-Square
Parts
required:

Parts required:
3 of No. 2 | 1 of No. 3
5 of No. 37

Parts required: 2 of No. 2 1 " " 3


#### Model No. 1.14 Belt Gear

For Reversing Motion of Driven Shaft



# Model No. 1.15 Belt Gear

For Driving Shafts at Right Angles




# Model No. 1.8 Lever of the Third Order (Demonstration Model) Parts required: 2 of No. 2 4 " " 5 1 " " 18A 1 " " 22 1 " " 35 10 " 37 1 " " 57

The fulcrum is at one end, the load at the other and the power lies between the two.

#### Model No. 1.16 Pulley Block

Demonstration Model: 1 Fixed and 3 Movable Sheaves, Theoretical Mechanical advantage: 8 to 1



#### Parts required:


4	of	No.	1	2	of	No.	18a
3		13	2	3	,,	"	19в
6			5	4	"	**	22
2			11	15	"	,,,	37 44
2			12	1	"	"	52
2	,,		17	1	"	"	57

#### Model No. 1.17 Pulley Block

Demonstration Model:
3 Fixed and 2 Movable Sheaves.
Theoretical Mechanical advantage: 5 to 1

#### Parts required:

4	of	No.	1	4	of	No.	19в
7	,,	. ,,	2	4	,,	"	22
6	,,	**	5	6	,,	12	35
2 2 2 2 2	,,	,,	10	22	,,	,,	37
2	,,	,,	11	1	,,	,,	44
2	"	,,	16	1	,,	"	52
2	"	,,	17	1	,,	,,	57
2	,,	,,	18A	2	,,	"	126A



#### Model No. 1.18 Pulley Block


Demonstration Model: 1 Fixed Sheave and 2 Suspended Blocks. Theoretical Mechanical advantage: 4 to 1




#### Parts required:

4	of	No.	1	4	of	No.	19B	
1	,,	,,,	3	3	,,	,,	22	
4	,,	,,	5	10	,,,	,,,	37	
2	,,	,,	11	1	,,	22	44	
1	,,	,,	17	1	,,	,,	52	
2	,,	,,	18A	1	,,	4.	57	


#### Model No. 1.19 Belt Gear



## Model No. 1.20 Belt Gear




#### Model No. 1.21 Invalid Chair




#### Model No. 1.22 Letter Balance

				· P	arts	req	uired	:			
	of	No.	2	4	of	No	22	1 2	of	No.	48A
3.	,,	. 30	5	1	.,	22	24	1	- 27	D	52
1	,,		10	26	,,	2.5	37	2	,,	116	111c
2	"	**	12	4	,,	1)	37A	2	,,	,,	126
1	**	1)	18A	2	1,	21	38	2	**		126A
1	21	125	19в	1	11	21	44	1			




#### Model No. 1.23 Ticca Gharry




		F	ar	ts	re	quired	
* * *	-		13.9		1000		

4	of	No.	2	6	of	No.	12	122	of	No.	370-7
6	,,	"	5	2	,,	,,,	16	1	2)	,,	37 7 52 54
2	,,	"	10	4	,,	22	22	1	"	,,	54




#### Model No. 1.25 Truck with Sides




#### Model No. 1.26 Mechanical Saw

				Par	ts	requi	red:				
1	of	No.	2	1	of	No.	17	4	of	No.	38
8	,,	**	5	1	,,,	**	19s	1	,,	,,	44
1	,,	,,	10	3	.,,	21	22	4	,,	,,	48A
1	**	,,,	11	1		,,	24	1	,,	,,	52
4	,,	"	12	3	**	,,	35	2		17	125
1	**	,,	16	22	21	11	37	1	.,,		126A




The Strip 9 represents the saw. The Crank Handle drives through a belt 1 a short Rod journalled in a Double Bracket 2 and carrying a Bush Wheel 3. The latter imparts a reciprocating motion to the saw frame 4 through a 2½° Strip 5 loosely mounted on bolts secured to the Bush Wheel and to an Angle Bracket bolted to the saw frame. This frame slides on a 3½° Rod 6, which acts as a guide, passing through the frame and supported in a reversed Angle Bracket 7. A washer is placed on the Bolt 8 behind the Bracket 7. A vice to secure the objects in position for cutting consists of a Flat Bracket 10 mounted on a Bolt 11, a few turns of which causes the Flat Bracket to grip the object 12. The Bolt 11 enters a nut held between the Flat Trunnion 13 and 5½° Strip 14, which are spaced apart for the purpose by washers placed on the two bolts holding the Trunnion in position. The saw frame rests on the stop 15 when not in use. A 1° Pulley secured to the top of the frame acts as a weight and helps to steady the saw.

#### Model No. 1.27 Dinner Wagon




The two lower platforms are constructed out of pieces of ordinary cardboard, their outer edges resting on  $2\frac{1}{2}$  Double Angle Strips and their inner edges on Angle Brackets.

#### Model No. 1.28 Tip Wagon



#### Model No. 1.29 Aeroplane




- 3		E Line		Parts required:						•			
2	of	No.	2	2	of	No.	16	1	of	No.	48A		
5	,,	,,	5	2	,,	,,	22	1	,,	,,	54		
1	,,	,,	11	1	,,	,,	24	2	11	,,	90A		
6	,,	"	12	21	,,	,,	37	2	,,	,,,	100		

#### Model No. 1.30 Timber Drag




4 of No. 2 | 2 of No. 16 | 8 of No. 37 2 , , 11 | 4 , , 22 | 4 , , 48A

#### Model No. 1.31 Lawn Mower




#### Model No. 1.32 Tandem Car



Parts required:


4	of	No.	2	26	of	No.	37
8	,,	.,,	5	5	"	1)	48A
2	17	**	12	1	**	- 19	54
4	"		10 10p	2	. 11		126a

#### Model No. 1.33 Mechanical Hammer




Parts

required:




The figure at the right of the model is arranged to work to and fro when the Crank Handle is rotated. The Bolts 1 and 2 are both secured by two nuts as in Standard Mechanism No. 262.

#### Model No. 1.35 Top




To spin the top wind a length of cord round the rod, as shown, place on a smooth surface and give the cord a sharp pull. When the cord is clear of the rod remove the 51" Strip and the top will continue to spin for a considerable period.



Model No. 1.37 The Invalid

When wheeled along the table the "invalid" appears to push himself energetically along. His neck is a Flat Bracket: his right (or propelling) arm consists of one Angle




his left arm-the hand of which is bolted loosely to the chair-is formed by three Angle Brackets. The chair is composed principally of two Sector Plates and four  $5\frac{1}{2}$ " Strips, and it runs on three 1" Pulley Wheels-one in front and two at the back. One of these (not visible in the illustration) drives by cord another 1" Pulley Wheel, the shaft of which also carries a Bush Wheel 1. As will be seen, a 21" Strip is pivoted at one end to this Bush Wheel and at the other end to a second 21" Strip 2, which, rocking about an axle journalled through its centre hole, is again pivoted to the invalid's hands.



passes over the 1" fast Pulleys at each end of the model. One of the Pulleys is secured to a Crank

Handle, by means of which the model may

be operated. The Meccanitian runs on the upper half of the endless cord, the lower half being attached to one of his feet.



This is a model of an ancient engine of war, resembling the crossbow The 3½" Strip 1 is bolted firmly to the Double Angle Strip 2, which is prevented from turning by the addition of Angle

from turning by the addition of Angle Brackets as shown. A Double Bracket 3 slides on the Strip 1 and is secured to a piece of cord. On rotation of the Crank Handle 4, the Strip 1 is pulled backward until the Double Bracket 3 slips off its end. The Strip then flies forward and strikes the missile, which consists of a 2" Rod placed ready in the Double Bracket 5.

Parts requ	ired:	
------------	-------	--

4	of	No.	1	2	of	No.	16	1	of	No.	44
4	,,	11	2	1	,,		18a				
1	,,		3	3	,,		19в				52
2	13		11	. 1	,,		19s	1	12	23	90a
2	,,	3.2	12	4	12	,,,	22	2	,,	21	126a
				21			3/	1			



4	of	No.	1	2	of	No.	17	1	4		Pillon
4	,,	32	2	1	,,	,,	19s				
1	32	"	3	4	,,	,,	22				
5	,,	23	5	1	32	22	23	2	of	No.	48A
3	11	2.3	10	6	,,	12	35	1	,,	12	52
4	33	1,	12	34	,,	12	37	2	21	12	54
2	12	1)	16	2	,,	13	38	1	21	,,	126a

#### Model No. 1.41 Double-Action Piston Connection


		Р	arts r	equi	red	:		
2 6 1 5 4 2 3 2 1	of	No. """"""""""""""""""""""""""""""""""""	1 2 3 5 10 11 12 19B 19s			No.	35 37 37A 48A 52 90A 111c 126A	

#### Model No. 1.43 Telpher Span

#### Model No. 1.44 Mountain Transport

Parts required:


2 of No. 1 | 3 of No. 5 | 2 of No. 16 2 ,, ,, 2 | 2 ,, ,, 11 | 4 ,, ,, 22 18 of No. 37 | 1 of No. 52 3 ,, ,, 48A | 1 ,, ,, 54



#### Model No. 1.42 Ladder on Wheels

Parts required:

4 of No. 1 | 16 of No. 37 2 ,, ,, 16 | 6 ,, ,, 48 4 ,, ,, 22 | 1 ,, ,, 52




This model will provide many hours of enjoyment. The cords may be made to any length to allow the load to be carried from one side of the room to the other, and, if necessary, a better grip may be obtained by winding the operating cord twice round the Pulley on the Crank Handle. The open sides of the bucket may be closed with cardboard so that it may be loaded with marbles, beads, etc. The bed of the Telpher may be screwed on to a solid base with ordinary wood screws to give better support.

The Pulley Bracket, and that securing the cord on which the bucket travels should

be screwed in a suitable position on the opposite

side of the room.



#### Model No. 1.46 Bow and Arrow

Parts required:
1 of No. 1 | 1 of No. 16




#### Model No. 1.47 Friction Grip Tongs

The hoisting cord is attached to the Double Bracket 1. The joints 2, 3 are lock-nutted, so that when the grip is raised the  $\frac{1}{2}$ " loose Pulley Wheel 4 slides upward between the  $2\frac{1}{2}$ " Strips 5, and the grip closes upon the block of wood or other material placed between its jaws.

#### Parts required:

3	of	No.	2	1	of	No.	11
8	,,	1,	5 10	1	,,	,,	23
4	*					,,	35
		12	of N	0.	37		




#### Model No. 1.48

#### Cum Bak


Parts required:

1 of No. 18A
2 ,, ,, 19B
2 ,, ,, 22
1 ,, ,, 23
1 ,, ,, 37
4 ,, ,, 48A



A short length of elastic is doubled and stretched between the centres of the 3" Pulley Wheels. weight, consisting of two 1" fast Pulley Wheels and a 1½" Rod, is suspended from it in the middle of the drum. When the Cum Bak is rolled along any smooth level surface, the elastic becomes twisted and stores up sufficient energy to return the drum to its starting point. If the mechanism is concealed by a thin cardboard covering, the model will cause much amusement by its mystifying behaviour.


#### Model No. 1.49 Aeroplane




#### Model No. 1.50 Gangway

Parts required:


4	of	No.	2	1	of	No.	16	122	of	No.	37	12	of	No.	100
2	))	11	5	1	,,	11	22	4	,,	,,	48A	1			111c 126a
3	,,		10	1	,,	- 10	23	1	,,	,,	52	2	,,	21	126A
1			12	1 4			35	1			54	1			





The weighted curved Strip normally holds the end of the  $5\frac{1}{2}''$  Strip against an Angle Bracket, allowing the signal arm to fall to the "all clear" position. Any train passing the signal however, strikes the opposite end of the  $5\frac{1}{2}''$  Strip, and by means of the cord shown, raises the arm to indicate "danger." The Curved Strip moves to allow the end of the  $5\frac{1}{2}''$  Strip to pass over it, and is returned to its original position by reason of its weighted end. The signal then remains at "danger" until the mechanism is re-set.

#### Model No. 1.52 Horse and Cart




19B


Model No. 1.53 Drill


# 

., ,,




#### Model No. 1.54 Patent Luffing Crane






# Model No. 1.56 Truck




Parts
required:
2 of No. 16
4 " " 198
8 " " 37
2 " " 48A
1 " " 52
2 " " 100

Fig. 1.55A


#### Model No. 1.57 Steam Shovel





#### Model No. 1.58 Cot on Wheels




#### Model No. 1.59 Chair











# Model No. 1.66 Jib Crane




#### Model No. 1.67 Centrifugal Governor




The 3" Pulley Wheel is bolted to the  $5\frac{1}{2}$ "  $\times 2\frac{1}{2}$ " Flanged Plate as shown, and the Rod 6 is free to rotate in its boss. The Bolts 1, 2, 3, are provided with lock-nuts. When the engine to which the governor is attached works at too great a speed, the 1" fast Pulley Wheels 4 fly outward and lift the two Double Brackets 5. In actual practice this movement is utilised to close the engine valves and so reduce speed.

#### Model No. 1.68 Stone-Sawing Machine




#### Model No. 1.69 Elevated Crane



The base of the swivelling portion of the crane consists of a 3" Pulley Wheel 1, which has a 3\[ \frac{1}{2} \] Axle Rod nipped in its boss. The Rod is journalled in two 2\[ \frac{1}{2} \] Double Angle Strips 2 and 3 secured between the Sector Plates 4. The brake cord 5 passes round the 3" Pulley as shown, and is tied to one of the holes in the Bush Wheel 6. The cords 7 serve merely to support the weight of the jib.

#### Model No. 1.70 Rowing Boat



#### Parts required:


4	of	No.	2	4	of	No.	35
4	,,	,,	5	24	,,	,,	37
4	,,	,,	10	3	,,	,,	48A
7	,,	,,	12	1	,,	,,	52
2	,,	,,	16	2	,,	,,	54
1	,,	,,	22	1	,,	,,	111c

#### Model No. 1.72 Weather Vane

#### Parts required:

3	of	No.	1	14	of	No.	37	
2	,,	"	2	1	,,	1)	52	
1	,,	,,	11	1	,,	,,	54	
2	,,	12	12	1	,,	2)	111c	
1	,,	15	24	2	,,	"	126	

#### Model No. 1.73 Violin and Bow




#### Parts required:

4	of	No.	2	1	of	No.	12 18a 35	5	of	No.	37	
1	,,	,,	5	1	7,1	,,,	18A	1	,,	2)	54	
1			11	2			35	1			126	


#### Model No. 1.74 Beam Engine


The connecting Strip 1 is attached pivotally by a Bolt and two Nuts (Standard Mechanism No. 262) to one end of the beam 2 and to the Bush Wheel 3. The Strip 4 is similarly connected to the other end of the beam 2 and to the Double Bracket 5 attached to the piston rod. The short rod carrying the flywheel 6 is journalled in a  $2\frac{1}{2}$ " Strip supported by the Trunnion 7 and in a reversed Angle Bracket bolted to the  $2\frac{1}{2}$ " Strip.





#### Model No. 1.71 The Wrestlers






#### Model No. 1.80 Electric Elevator

#### Model No. 1.81 Mounted Cowboy


#### Model No. 1.83 Coaster



#### Parts required:

4	of	No.	1	1 3	of	No.	35
6	,,	,,	2	34	,,	,,	37
4 2 3 3	13	23	5	1	"	.,,	38
2	,,	21	12	1	,,	,,	48
3	,,,	21	16	6	13	22	48A
3	1,	23	19в	1	,,	1)	52
4	"	23	22	2	21	12	54
1	"	"	24	2	,,,	"	100
		2	of I	Vo.	125		

Electric Motor (not included in Cutfit)





required: 2 of No. 2 22 of No. 37 | 4 of No. 48A 2 ,, ,, 37A 1 ,, ,, 52 2 ,, ,, 126A


Model No. 1.84

Model No. 1.82 Howitzer










#### Model No. 1.85 Travelling Crane

The jib 1 is pivoted to the Flat Trunnions 2, which are bolted at 3 to Angle Brackets secured to a Bush Wheel. The latter is mipped to a 2" Rod 4 passing through the Plate 5 and further supported in a Double Angle Strip 6. A Washer and Spring Clip mounted on the Rod 4 below the Strip 6 secure the crane to the carriage. The jib is supported by means of cords 7 tied to 21" Strips 8, the holes of which engage the shank of a bolt passed through the Sector Plate 9, and its elevation may be altered by inserting this bolt in different holes in the Strips 8. The cord 10 of the brake lever is wound once round the Crank Handle, between two Washers.

#### Model No. 1.86 Bicycle


Model No. 1.88 Gymnast



15 1	equi.	icu	•		6
3	2	of	No.	17	
5	1	,,	,,	18A	
10	2	,,	,,	19B	
11	. 2	,,	22	22	
12	1	,,	2.1	24	
	4	,,	21	35	
	13	**	**	37	
	4	,,	11	37A	
	3 2 4 2	"	1.5	38	
	2	,,	13	90A	
	4	,,	,,	111c	
	2	7,1	,,	125	
	1	,,	12	126A	
	1	"	1)	126a	

#### Model No. 1.87 Luggage Truck

#### Parts required:




	,,	176	1	4	"	"	70 K				$\forall$	y		
					0		61					P re	arts	s ire
			1	"						7-1	).	4	of	N
					,ast				رر			3	,,	,
١.		-	100		der		149			Sec.		3	"	,
ú		₹	est.			J.				,		4	21	-
r					7	46	A A	4	0			1	21	
	-40				1	17)	7			標		1	**	1
Ź					٠,		100		- 4			3	,,	

	Parts	requ	ired:
1	1 -6	NI	100


4	of	No.	2	1	of	No.	19s	1	of	No.	44
7	,,,		5				22	3	,,	1,	48 A
1	,,	.,	10	1		"	23			.,	
2	,,	* 21	12	5	12		35	4	,,	,,	54
2	,,		16	27	"		37		,,	,,,	
2	,,	1)	17	6		,,	38	2	,,	,,	126A

3 of No. 35

One of the 2½" Strips representing the arms of the gymnast is bolted to a Bush Wheel secured on a 31" Rod. When the Crank Handle is rotated the gymnast turns complete somersaults in a very amusing manner. The gymnast's "arms" must be pivoted to the Angle Brackets forming his shoulders by means of Bolts and Lock-Nuts.




#### Model No. 1.94 Motor Lorry




#### Model No. 1.95 Disappearing Meccanitian

The bottom of the box-like portion of the model consists of a  $5\frac{1}{2}'' \times 2\frac{1}{2}''$  Flanged Plate; three  $5\frac{1}{2}''$  Strips bolted to upright  $2\frac{1}{2}''$  Strips form each side and each end consists of three  $2\frac{1}{2}'' \times \frac{1}{2}''$  Double Angle Strips. The lid 1, which is mounted pivotally on an Axle Rod 2, consists of two Sector Plates bolted together. Elastic bands are tied to the sides of these Plates and connected to Rod 3 passed through the bottom of the box. The ''Meccanitian'' 4 also is connected to this Rod by pieces of elastic. On pressing the end of the rear Sector Plate the lid opens sufficiently to allow the figure to be drawn inside and then snaps back into place. A Cranked Bent Strip 5 is bolted at the back of the figure and rests, against the edge of the Sector Plate.



#### Model No. 1.96




#### Model No. 1.97 Field Roller

Parts required:	:
-----------------	---


2	of	No.	1	1	of	No.	16	6	of	No.	48a 90a 126
3	,,	"	5	2	,,	,,	19B	2	1)	,,	90A
6	,,	22	12	30	33	33	37	2	,,,	. 12	126




Model No. 1.98
Elevator



Two cords stretched between the base plate of the model and the upper structure are passed through holes in the Double Angle Strips of the cage to form guides. A further cord is tied to the upper Double Angle Strip, and after being led over the 3" Pulley at the head of the model is tied to the shaft of a Crank Handle.






#### Model No. 1.108 A Sudden Appearance

The Sector Plate 1, forming the lid, is carried pivotally on an axle rod that passes through its sides three holes from the end, and the rear Sector Plate 2 is pivoted in a similar manner, excepting that the rod in this case passes through the fourth hole from the end. Pieces of thin elastic are tied to the end holes in each side of the front Sector Plate at its widest end, and are connected to a Rod journalled in the sides

of the box. The " Meccanitian" 3 is placed face downward inside the box with his feet towards the far end of the model. The tension of the elastic holding the lid I should be sufficient to keep him in this position. On tilting the Plate 1 slightly, however, he will suddenly shoot out of the box, drawn by the elastic bands 4 connected to the 31" Axle Rod 5.

Parts required:
4 of No. 1
4 " " 2
8 " " 5
5 " " 10
4 " " 16
1 " " 22
8 " " 35
29 " " 37
4 " " 48
1 " " 52
2 " " 54



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A)

#### Model No. 1.109 Double Draw Bridge

4 of No.

	Pa	rts	requ	ired	:			
1	1	of	No.	19s	12	of	No.	38
2	2	,,	"	22	6	21	1)	48A
16	8	,,,	"	35	2	,,	23	48A 126A
- 1	16	,,	"	37	1			_


#### Model No. 1.112 Motor Cyclist and Pillion Rider

Parts required:

4	of	No	. 2	2	of I	No	. 17	2	of I	No.	48A	
9	,,	2.5	5	4	"	"	22	2	23	11	90a	Á
		2,1	10	1	,,	21	24	2	1)	,,	125	Ĭ.
			11		,,	,,	35	2	,,	,,	126A	1
8	,,	,,	12	30	,,	,,	37					4
1	,,	,,	16				1			-46		14

required:

4 of No.




The figure 1 is loosely attached by lock-nutted Bolts 2 to the Sector Plate 3 and is connected to the Bush Wheel 4 by the pivotally-attached  $2\frac{1}{2}$ " Strip 5. The  $1\frac{1}{2}$ " Rod carrying the Bush Wheel 4 is journalled in the Cranked Bent Strip 6, the 1" fast Pulley 7 being connected to the road wheel by a cord as shown.




Tappet Valve Demonstration

Model No. 1.111


	art	s ired		
16	equ.	rea	•	
1	of	No.		
1	31	1)	5	
1	,,	,,	10	
1	32	23	11	
3	23	11	12	
2	,,	21	16	
1	,,	11	17	
1	12	,,	18A	
4	,,,	12	22	-
1	,,	15	24	
5	,,	"	35	
15	,,	3)	37	1
5	,,	,,	37 A	
4	12	*2	38	
1		"	48A	
1	. ,,	٠,	52	A
1	,,	**	54	
2	,,	1,	111c	
2		,,	126A	




Model No. 1.113 Chinese Windlass



The upper end of the Strip 1 is connected pivotally by a Bolt and two Nuts to the crosshead Bracket 2. The crankshaft is built up as follows: Two Angle Brackets are each secured rigidly to the boss of a Pulley Wheel and are connected to each other by a 3 Bolt carrying three Nuts. The Nuts are screwed tightly against the Brackets, sufficient space being left between the inner pair to enable the connecting Strip 1 to turn freely. The valve Rod 5 is operated by the Flat Bracket 4 that is clamped between two further 1 Pulleys on the crankshaft in such a way that its protruding end serves as a cam.




#### Model No. 1.114 Pile Driver




The winding cord is passed round the Pulley at the top of the model and is fastened to an Angle Bracket that is hooked under the protruding portion of a Flat Bracket bolted to the top of the driving head. When the Angle Bracket reaches the Pulley at the top it is pushed out a little, thus releasing the driving head.






The treadle lever is connected pivotally to a  $3\frac{1}{2}''$  Strip by a Bolt and two Nuts. The upper end of this Strip 2 is similarly connected to a  $2\frac{1}{2}''$  Strip that is clamped tightly between two Pulleys on the hammer Rod 4. Pressure on the treadle causes the hammer to descend on the work. When the treadle is released a weight pulls the hammer back to its original position.

#### Model No. 1.116 Heavy Duty Scales



#### Model No. 1.117 Horse Rake




The 2½" Strip 1 pivots about the wheel axle. A 2½" Strip 3 is connected by a Bolt and two Nuts to the Strip 1 and the Rod 2 passes through its other end. On pulling the lever 1 towards the shafts the rake is lifted from the ground.

Model No. 1.118 Gravity Conveyor

Parts required:

4 of No. 1 | 36 of No. 37
3 ,, ,, 2 | 3 ,, ,, 37A
8 ,, ,, 5 | 1 ,, ,, 48
8 ,, ,, 12 | 3 ,, ,, 90A
3 of No. 111c



#### Model No. 1.126

# Crosshead Demonstration

# Model

2 of No. 126A




		Pa	rts	requ	irec	1:	
2	of	No.	1	1 1	of T	No.	24
4	,,	,,	2	3	,,	,,,	35
9	,,	2.1	5	20	,,,	"	37
2	12	11	16	2	,,	11	48A
1	,,	33	23	1	,,,	11	52




This is an apparatus for determining the forces that act at the crosshead of a reciprocating engine. The upper inclined length of cord represents the connecting rod and the lower, or vertical portion, the piston rod. The pull on the third cord indicates the pressure exerted on the slide bars of the engine due to the angularity of the connecting rod.

#### Model No. 1.127 Drop Stamp



#### Model No. 1.128 Blacksmith





2 of No. 126

Model No. 1.124 Eccentric Dancers

Parts


required:

6 of No. 5

20 of No. 37

" 126A





#### Model No. 1.132 Motor Van

# Parts required: 3 of No. 5 | 1 of No. 35 1 ,, , , 11 | 17 ,, , , 37 1 ,, , 12 | 3 ,, , 48A 2 ,, , 16 | 1 ,, , 52 1 ,, , 17 | 1 ,, , 54 4 ,, , 22 | 3 ,, , 90A 1 ,, , 23 | 1 ,, , 111c 1 ,, , 24 | 1 ,, , 125 1 of No. 126A

The steering mechanism is shown more clearly in Fig. 1.132A. A length of cord is given two or three turns round the steering column, and is held in position by a Spring Clip, its ends being tied to a  $2\frac{1}{2}'' \times 2\frac{1}{2}''$  Double Angle Strip. The latter is pivoted to the  $5\frac{1}{2}'' \times 2\frac{1}{2}'''$  Flanged Plate of the lorry by means of a Bolt and two Nuts (see Standard Mechanisms Manual. Detail No. 262).





Fig. 1.132A

#### Model No. 1.131 Boat

Parts
required:

4 of No. 1
2 ,, , 2
1 ,, , 5
2 ,, , 11
21 ,, , 48A
1 ,, , 52
2 ,, , 90A
2 ,, , 125



Model No. 1.133 Revolving Hammerhead Crane


#### Model No. 1.130 Double Cable Key Parts required:


Parts required:

2 of No. 2 | 1 of No. 52

2 ,, ,, 22 | 2 ,, ,, 111c

4 ..., 37 | ..., 111c






#### Model No. 1.139 Butter Churn


#### Model No. 1.141 Cable Railway


#### Model No. 1.144 Man and Boy



1 of No. 19s

Parts required:







#### Model No. 1.142 Candle Stick

-	arts		
re	qui	red:	
2	of	No.	11
4	,,	1)	12
1	,,	"	19:
4	,,	23	37
1	,,	23	111
1	,,	.,,	125





Model No. 1.143 Machine for Tracing a Locus




Parts required:


1	of	No.	2	4	of	No.	35
1	12	"	5	4	1)	,,	37
1	,,	12	11	3	,,	22	37A
1	23	22	12	4	,,	,,	38
1	,,,	12	17	1	2.0	,,	54
1		32	18 A	2	,,	33	111c
1	,,	12	24	1	2.5	37	125


The 5½" Strip is pivoted to the 2½" Strip by means of a Bolt and two Nuts, and the 21" Strip is similarly pivoted to the Sector Plate. By revolving the 21" Strip about its pivot, the vertical 11 Rod can be made to trace a locus. If the positions of the 11" Rod and

the 51" Strip are altered, several different loci may be traced. Machines of this type are of advantage in assisting in the design of engine connecting rods.



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A)








Parts

#### Model No. 1.162 Punching Machine



#### Model No. 1.163 Scales required: 2 of No. 2

2	23	,,	11		
1	,,	,,	18a		
2	,,	,,	35	A STATE OF THE PERSON OF THE P	
8	"	13	37		
1	,,	. ,,	52		
2	,,	2.2	54		
2	1)	,,	126		
	1	2			
4	4	4			

Parts	r	eq	ui	re	d	:
2	1	4		0		

	01	110.	-	. 4	OI	TAO.	44
7	,,,	,,,	5	1	,,	,,	48A
2	,,	,,	12	1	23	"	52
2	17	"	17	1	,,	"	54
1	,,,	**	19s	1	"	,,,	57
- 4	,,,	**	22	2	,,	23	126A
1	23	.00	23	1	N		
2			35				

Model No. 1.164 Extended Ash Tip

2 of No. 18A | 6 ,, ,, 111c 2 ,, ,, 125 2 ,, ,, 126 2 ,, ,, 126A

Parts required:


The trolley is operated by means of a cord that is wound round the 11 Axle Rod carrying the Bush Wheel, both ends of the cord being secured to the trolley. The bucket is suspended from a cord that winds on to the Crank Handle, and it is tipped by lowering it until a short cord that is attached to the bottom of the bucket and to the trolley, becomes taut. Further lowering causes the bucket to swing over.

The Sector Plate of the Crane in the above model is pivoted to the base with a fast Pulley above and below.

Model No. 1.165 Swivelling Crane




		Pa	arts	requ	irec	1:		
4	of	No.	1	1	of	No.	24	
6	,,	,,	2	7	,,	,,	35	
2 5 8	,,	23	5	35	21	,,	37	
5	,,	100	10	1	£ ,,	1)	48A	
8	,,		12	1	21	12	52	
2	,,	,,	16	1	,,	,,	54	
1	1.	"	17	2		1,	125	
4			22	2			1264	



Parts required: 3 of No. 5

The steering gear is shown in Fig. 1.167a. The front wheels are carried in a  $2\frac{1}{2}'' \times \frac{1}{2}''$  Double Angle Strip 1, which is mounted pivotally by a Bolt and two Nuts (S.M. 262) to a  $2\frac{1}{2}''$  Strip 2 secured to the  $5\frac{1}{2}'' \times 2\frac{1}{2}''$  Flanged Plate.

#### Model No. 1.168 Bagatelle Table









Fig. 1.167A

2	of	No.	2	1	of	No.	24
1	,,	11	3	6	,,	,,	35
2	,1	12	5	15	,,	**	37
2	,,	,.	1 1	2	,1	.,	37A
2	,,	,,	12	3	,,	,,	48A
1	11	"	17	. 1	,,	,,	52
2			18a	2.			125










#### Model No. 1.181 Submarine

Parts required:


4	of	No.	1	2	of	No.	35
5	,,	21	10	28	,,	23	37
2	,,	22	11	3	,,	"	37A
8	,,	,,	12	2	,,	,,	38
2	,,	))	17	1	,,,	1)	48
3	,,	- 33	22	1	,,	12	48A
1	,,	1)	24	2	,,	1)	125
				1 2			126

Trunnions are bolted to the side 121 Strips, and a bolt passed through their inner extremities secures a 1" Reversed Angle Bracket and an Angle Bracket. The former is attached to the upper 121 Strip while the Angle Bracket is connected by means of a Flat Bracket and a further Angle Bracket to the lower Strip.



Parts required:

2 of No. 18A 4 of No.




#### Model No. 1.184 Acrobat on See-Saw

		•	red:				F		3	of	No.		
- 1	3	ot	No.	1			3.3		1	,,	,,	24	
	6	,,	23	2	600	DI.	* //		5	,,	,,	24 35	
	4	,,	,,,	5	1-	/	1		32	"	,,	37	
	3	21	1)	10	A	V/	194	,	2	,,	"	37 48 a	
	2	,,	,,	11	V.	- P		~	1			52	
	4	,,	,,	12	•	Assis	9	_ 5	1	"		1110	
	2	,,	,,	16	2-	Z			î	,,		126A	
	1	,,	12	18A	A		• (		÷	11	,,,	1201	
	1	,,	,,	19B	A		4.7						

The 1" Rod 1 is journalled in the end holes of two 53" Strips 2 and in the Flat Trunnion 3 which joins them. It is held in position by two Spring Clips, placed on either side of the 51/2" Strips 2.






#### Model No. 1.187 Rotating Crane

		Pa	ırts r	equi	red	:	
4	of	No.	2	1	of	No.	24
9	. 19	,,	5	5	,,	"	35
2	1)	22	10	25	1)	32	37
1	12	12	11	4	1)	23	48A
2		,,	16	1	32	22	52
1	15	11	17	1	,,	21	54
1			190	1			57

#### Model No. 1.188 Hooke's Coupling



#### Model No. 1.186 Revolving See-Saw

1	of	No.	2	1	of	No.	24
3	,,	23	5	2	,,	32	35
2	"	23	-11	25	13	,,	37
1	22	1)	12	5	12	2,1	38
į	2.7	12	16	1	,,	11	44
			17	- 4			10.

Parts required:

2 of No. 126




2	of	No.	11	7	of	No.	35
2	12	21	12	12	,,	23	37
3	12	,,,	16	1	12	13	48
2	,,	,,	19в	2	12	21	48
1	,,	,,	19s	1	,,	,,,	52


#### Model No. 1.189 Band Brake

Dorte voguinad .

								ıırea					Į.
l	1 2 1	of "	No. "	2 5 12	1 2 1 10	of ,, ,,	No.	19s 22 35 37	1 2 1	of ,,	No.	52 54 111c	
												1	
		J											





#### Model No. 1.190 Rat Trap



The "bait" consists of a 1″ fast Pulley and a  $\frac{1}{2}$ ″ loose Pulley suspended by means of a cord from a Double Bracket. The latter is bolted to a  $1\frac{1}{2}$ ″  $\frac{1}{2}$ ″ Double Angle Strip that is free to turn on a 2″ Rod journalled in a pair of Angle Brackets. A Flat Bracket bolted to the Double Bracket engages a second Double Bracket on the end of a  $5\frac{1}{2}$ ″ Strip that is bolted to the door of the cage. If the "bait" is touched, the heavily-weighted door falls into place, and is prevented from re-opening by catches formed from Flat Brackets secured to  $5\frac{1}{2}$ ″ Strips that are bolted to the trap by their extreme ends and act as springs.

#### Model No. 1.191 Toast Rack






#### Model No. 1.195 Gramophone

# 

#### Model No. 1.197 Lancer

1	of	No.	2	
1	,,	,,	3	
9	,,	23	5	
2		1,7	10	
2	,,	,,	11	
5		12	12	
2	,,	,,	16	
1	,,	,,	19s	
4		,,	22	0
1	,,	2.5	24	A
1	,,	,,	35	1
27	,,	11	37	
1	21	12	48A	•
1	,,	,,	52	
1	,,	,,	54	
4	.,	,,	90A	
1	,,		126A	

#### Model No. 1.198 Stamping Machine



#### Model No. 1.196 Lorry Crane




1	2	of	No.	16
1	1	,,	,,	17
1	1	,,	"	18A
	4	,,	1)	19 <sub>B</sub>
	1	,,	1)	19s
	3	,,		22
	1	,,	12	23
	1	,,	21	24
	3	,,	23	35
	29	22	23	37
	1	21	1)	44
	5	21	17	48A
	1	,,	,,	52
	1	,,	,,	54
	1	ñ	23	57
	2	,,	,,	125

Model No. 1.199 Lazy Tongs

2	of	No.	1	1	of	No.	23 37 37 <sub>A</sub>	2	of	No.	48A
4	,,	1)	2	12	,,	"	37	2	,,	,,	111c
4	,,		5	10	,,	**	37A				




2 of No.



The ladle pivots about a 3½" Axle Rod carrying a 3" Pulley at each end in addition to a Bush Wheel and a 21/4" Strip. The two latter parts are bolted to the side flanges of the Sector Plates and the Bush Wheel is nipped in position on the Rod. The pivot about which the superstructure turns is shown in Fig. 1.200A.

#### Model No. 1.201 Boat Steering Gear

Parts required:



#### Model No. 1,203 Elevated Jib Crane Parts required:

A 1" fast Pulley Wheel secure.1 to the armature spindle of the Electric Motor is connected by an endless cord to the 3" Pulley Wheel 1. A 1" fast Pulley 2 on the same Rod as the latter is similarly connected with a second 3" Pulley Wheel 3. A cord wound on the Rod to which the latter is secured carries the load hook. The jib is supported by two cords 4, and the whole superstructure, which is secured to the 3' Pulley Wheel 6, is capable of revolving with the Rod 5. The latter is journalled in two  $2\frac{1}{2}'' \times \frac{1}{2}''$  Double Angle

Strips secured between the Sector Plates in the base of the model.






Fig. 1.200A

3 of No. 22


The 7/32'' Bolt 1 is gripped by the Set-Screw of the Bush Wheel. The lower end of the Rod 2 of the Gyroscope enters the boss of the Bush Wheel and rests on the shank of the Bolt 1.








(not included in Outfit)



#### Model No. 1.209 Gong



### Model No. 1.211


Begin to build this model by making the platform from a Flanged Plate and 12½" Strips. The drive from the Pulley on the Crank Handle is taken to a 1" Pulley fast on the vertical 2" Rod, another similar Pulley being secured to this Rod beneath the Plate.

The arms are formed of four  $5\frac{1}{2}''$  Strips bolted to a Bush Wheel fast on the 2" Rod.

#### Parts required:


4	of	No.	1	3	of	No.	22
4	,,	,,	2	1	,,	23	24
6	,,		5	6	,,	23	35
4	23	,,	10	22	,,	1)	37
2	21	1)	16	4	23	,,	48A
1	2.1	12	17	1	23	"	52
1	,,	,,	19s	2	2.3	"	54





#### Model No. 1.213

#### Travelling Crane



#### Parts required:


4	of	No.	2	1	of	No.	22
1	,,	,,	5	9	,,		
3	"	23	12	1	,,	1,	52
1			16	1			54


#### Model No. 1.210 Emery Wheel


#### Parts required:

37 18a
Q A
52
lic ,
25
26A
ery
er
411
1


1	of	No.	3	1	of	No.	35
9	"	,,,	5	30	,,	,,	37
5	,,,	"	10	1	,,	,,,	52
8		32	12	1	"	"	111c
1	"	"	17	2	,,	,,,	125
1	"	33	22	2	13	"	126A







#### Model No. 1.219 Deck Chair



#### Model No. 1.220 Potter's Wheel

#### Parts required:


		Pai	rts r	equ.	ired	. :		
3 4 1 1 1	of	No.	2 5 16 18 <sub>A</sub> 19 <sub>B</sub> 19 <sub>S</sub>	3 1 1 12 3 1	of ,,	No.	22 24 35 37 48 <sub>A</sub> 52	( Commonwealth of the Comm
								v

#### Model No. 1.221 Luggage Cart





	distant.			1	18	of	No.	37
Parts	4 0	f	No.	5	1	,,	"	52
	4	,,	93	12	2	21	2,1	90 A
required:	1	,,	23	16	2	,,	-11	100
2 of No. 2	2	,,	,,	22	2	,,	1)	126a


#### Model No. 1.222 Elevator



















#### HOW TO CONTINUE

This completes our examples of models that may be made with MECCANO Outfit No. 1. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 1A Accessory Outfit, the price of which may be obtained from any Meccano dealer.



Parts

#### Model No. 2.6 Treadle Lathe




The 21 Strip 2, forming the treadle, is attached pivotally by means of a bolt and two nuts to the Angle Bracket 1. One end of a further  $2\frac{1}{2}$ " Strip is connected by the same means to the  $2\frac{1}{2}$ " Strip 2, and the other end is mounted on a threaded pin secured to the 3" Pulley Wheel.

#### Model No. 2.7 Revolving Truck

#### Parts required:

1	of	No.	16	2	of	No.	22A	1	of	No.	52
2	,,	.,,	17	4	,,	,,,	35 37	4	33	,,	125
2			22.	6			37				




#### Model No. 2.8

# Gong Parts required: 7 of No.

,, 125

Model No. 2.9 Hay Tedder




Model No. 2.10 High Level Bridge

		2 41		dan	ou.			
6	of	No.	1	2	of	No.	11	
4	21	1)	2	1	37	"	15	
2	1)	32	5	1	3)	23	22	
2	,,,	12	8	27	,,	,,,	37	
		1	of 1	Vo.	54			



#### Model No. 2.11 Elevator

#### Model No. 2.12 Fire Escape




The ladder is elevated on operation of the crank handle 1, which winds in a cord tied to the Double Angle Strip 2. Angle Brackets bolted to the  $12\frac{1}{2}$ " Angle Girders 12 are attached pivotally to the  $5\frac{1}{2}$ " Strips 13 by means of Bolts and Nuts (S.M. 262), and the action of winding in the cord thus causes the ladder to swing upward. It is prevented from falling by the friction of the 1" Pulley Wheels 10 (Fig. 2.12a), which press against the two Sector Plates. When the ladder is fully elevated, its lower ends act as brakes to prevent the road wheels from revolving.

A second cord is wound upon the Rod 3. One end is then carried over the  $\frac{1}{2}$ " loose Pulley Wheel 4 and tied to the  $2\frac{1}{2}$ " Strip 5, the opposite end being carried directly to the same Strip and secured to it. When the handle 6 is turned, the two ends of the cord are wound and unwound simultaneously, and the ladder is extended or shortened as required. A permanent brake is provided by a cord passing over the 1" Pulley Wheel 7 and having both its ends secured to the  $2\frac{1}{2}$ " Strip 8. The Strip 8 is bolted firmly to the Angle Bracket 9 (Fig. 2.12A) and keeps the brake continuously in action.

#### Model No. 2.13 Pit Head Gear

(Electrically Operated)



# Model No. 2.14 Pit Head Gear (Hand Operated)


This is an alternative construction of the base of Model No. 2.13, and shows how the Electric Motor may be dispensed with if necessary. Two 3" Pulley Wheels I are bolted together by four Double Brackets to form a drum on which the hoisting cord is wound. The cage is raised or lowered on operation of the handle 2, which is connected to the winding drum by an ordinary belt drive. The cage is prevented from overhauling by a hand brake that acts on the groove of a third 3" Pulley Wheel 3. The brake normally is applied by the weight of the  $\frac{1}{2}$ " loose Pulley Wheel 4, which is secured to the end of a  $5\frac{1}{2}$ " Strip that is bolted to the crank 5.




				ra	rts	requ	irea:					
6	of	No.	1	4	of	No.	22	2	of	No.	54	
7	37	.,,	2	1	,,	1)	23	2	,,	31	62	
3	12	,,	5	1	2.5	12	24	2	,,	**	99	
4	,,	,,,	8	3	,,	"	35	2	,,	2,	100	
4	,,	,,	11	60	,,	,,	37	6	,,	,,	111c	
6	,,	,,	12	6	,,	,,	37A	1	,,	12	115	
4	,,	"	16	8	,,	,,	48a	2	,,	17	126A	
4	,,	,,	19B	1	,,	,,	52					

#### Model No. 2.15 Acrobat

4	of	No.	1	28	of	No.	37
2	,,	,,	3	6	,,	,,	.37A
5	,,	,,	5	5	,,	,,	38
2	,,	23	8	1	,,,	,,	45
2	,,	1)	10	1	,,,	,,	52
1	,,	"	15	1	,,	,,	54
2	,,	,,	19в	2	,,,	,,	62
2	,,	,,	20в	1	,,	1,	115
2			22	2			101




# Model No. 2.16 Travelling Jib Crane (Electrically Operated)



## Model No. 2.17 Travelling Jib Crane (Hand Operated)


This shows a section of Model No. 2.16 fitted for hand operation, thus dispensing with the necessity of the Electric Motor. In this case the hoisting cord is operated by the hand wheel 6, the Rod of which is controlled by a band brake 7. The end hole of the lever of the latter is pivotally mounted on the Rod 8. The luffing movement of the jib is effected by the Crank Handle 9. The operating cord passes round the Rod 10 attached to the jib, then round Rod 11 in the base of the model, again round Rod 10, back round Rod 11, and once more round Rod 10. The end of the cord is then tied to a Flat Bracket on the Rod 11.

10	of	No.	1	1	of	No.	11	4	of	No.	20в	7	of	No.	48A
11	,,	n /	2	1	,,	. ,,	15	4		2.1	22			**	52
2	,,	,,	3	1	,,	2.3	15A	1	,,	23	23	2	,,	"	54
6	,,	,,	5	5	,,	,,	16	1	,,	,,	24	1	,,		57
2	,,	,,	6A	2	,,	,,	18a	12	,,	23	35	1	,,,	,,	62
4	,,	"	8	1	,,	,,	19	57	,,	,,,	37	4	,,	12	90a
3	,,	,,,	10	4	,,		19в	1	,,	1)	48	1	12	21	111c
						1	of No	o. 1	15						



#### Model No. 2.18 Electric Truck


An underneath view of the truck is shown in Fig. 2.18a. The front axle is journalled in a  $1\frac{1}{2}''\times\frac{1}{2}''$  Double Angle Strip 1 that is free to turn on a Double Bent Strip 2, from which it is spaced by a  $\frac{1}{2}''$  loose Pulley. A length of cord is wrapped round the 1' Pulley 3, which is secured to the end of the steering column, and then passed through a Cranked Bent Strip 4 and secured to the Double Angle Strip 1 as shown. The brake cord 5 is attached to the Double Bent Strip 2, wrapped several times round the  $\frac{3}{4}''$  Flanged Wheels 6, passed through the Angle Bracket 7, and is finally attached to the Crank 8. The operating pedal consists of Double Brackets bolted to another Crank that is secured to the same Rod as the Crank 8.



# Parts required: 3 of No. 5 | 1 of No. 22a | 7 of No. 48a 1 ,, ,, 6a | 1 ,, ,, 23 | 1 ,, ,, 52 2 ,, ,, 11 | 4 ,, ,, 35 | 2 ,, ,, 62 1 ,, ,, 12 | 35 ,, ,, 37 | 3 ,, ,, 90a 1 ,, ,, 12a | 2 ,, ,, 37a | 1 ,, ,, 111c 3 ,, ,, 16 | 5 ,, ,, 38 | 1 ,, ,, 115 1 ,, ,, 17 | 1 ,, ,, 44 | 1 ,, ,, 126 3 ,, ,, 20b | 1 ,, ,, 45 | 2 ,, ,, 126a

#### Model No. 2.19 Coal Sifter

The  $5\frac{1}{2}$ " Strip 1 is pivoted to the Angle Bracket 2 by a bolt and two nuts. The Angle Bracket in turn is bolted to the Flanged Plate, which is suspended in such a way that it is free to swing to and fro. The other end of the  $5\frac{1}{2}$ " Strip is pivoted to the Bush Wheel 3.








Fig. 2.18A
Parts required:

		1 6	irts re	equir	ea			
9	of	No.	2	1 2	of	No.	35	
	,,	,,,	3 5	54	,,	,,	37	
2 8 2 4	,,	21		. 6	,,	- 22	37A	
2	11	21	6A	8	,,	,,	38	
	,,	,,	8	1	**	.,	45	
1	,,,	23	12	6		.,	48 A	
1	,,	"	16	1			52	
2 2	,,	.,	17	2 2	,.	**	54	
2	,,	1)	19B				99	
2	21	1)	22	6	,,	,.	111c	
1	,,	12	24	1	23	1.	115	




"The boiler of the engine is built up of  $2\frac{1}{4}$ "  $\times \frac{1}{4}$ " Double Angle Strips bolted to the Bush Wheel 1, and to two  $2\frac{1}{4}$ " Strips 2, which are joined together by Flat Brackets 3. A  $2\frac{1}{4}$ " Curved Strip (small radius) is bolted to the upper Strip 2. A cord is passed completely round two  $\frac{1}{4}$ " Flanged Wheels 4 secured to the steering column, and its ends are tied to the  $2\frac{1}{4}$ "  $\times \frac{1}{4}$ " Double Angle Strip 5. The Double Bent Strip bolted to the Strip 5 is pivoted by a bolt and two nuts to the Sector Plate.



# 3 of No. 12 3 " 16 1 " 17 1 " 18A 2 " 19B 4 " 20B 3 " 22 1 " 22A 5 " 35 60 " 37 5 " 37 5 " 37 1 " 45 1 " 52 2 " 54 1 " 62 3 " 90A 1 " 900 4 " 111c 1 " 125 2 " 126A

Parts required: 12 of No. 2


12	of	No.	2
5		,,	- 5
2	,,	,,	8
1	,,	,,	15A
1	,,	2.7	22
1	,,	23	24
1	3.2	,,	35
44	3,7	21	37
1	,,,	,,	38
1		,,	48
8	1)	,,	48 A
1	,,	,,	52
4	,,	22	90a
2	12	,,,	99
2	,,	,,	126



Model No. 2.22

Mechanical Hammer


Fig. 2.22A



Parts

required:

4 of No.





#### Model No. 2.24 Parts required: Motor Lorry

8	of	No.	2	1	$\circ f$	No.	15a	1	of	No.	24	4	of	No.	48A
1			3 1	2			16	1 12			35	1			E2
10	12	21	U	1			ISA	49			37	1 1			5.4
0	"	23	10	4			19B	- 3			38	2			62
1	"	"	15	2	17	"	22	1	,,,	12	45	2	,,	21	111c

Clockwork Motor (not included in Outfit)


The driving spindle of the Clockwork Motor is removed and in its place is inserted a  $3\frac{1}{2}''$  Rod forming the rear axle, the special Pinion inside the Motor being secured to this Rod, of course, instead of to the driving spindle. The steering is operated by a Bush Wheel on a vertical  $3\frac{1}{2}''$  Rod journalled in a Double Bent Strip. Cord is wound round the lower part of this Rod and its ends are secured one to each end of a Double Angle Strip carrying the front axle. A Crank is bolted to this Double Angle Strip and carries a short Rod that is journalled in the boss of a further Crank bolted





#### Model No. 2.26 Turntable


The two sides of the revolving portion are joined in the middle by two pairs of  $2\frac{1}{2}$ " Strips, each pair being overlapped three holes and bolted to the 3" Pulley Wheel 1. An Axle Rod secured in the latter is journalled in the bottom plate 2 and retained in position by a 1" Fast Pulley Wheel beneath the plate.



These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A)

#### Model No. 2.27 Spinning Top


# Model No. 2.29 Performing Meccanitian




The drum on which the cord is wound consists of two  $\frac{3}{4}$ " Flanged Wheels butted together. While the cord is being pulled, the top is held steadily on some smooth surface by means of the handle shown above. The handle is then lifted off, allowing the top to spin freely.

#### Model No. 2.28 Mat Frame

The Strips 1 are hinged to the frame in the following manner. Two Cranks 2 with their bosses facing inward are bolted to the Strips 1 and two Angle Brackets are secured to the frame. A Rod is then pushed through the holes in the Angle Brackets and secured in the bosses of the Cranks. A Double Bracket fastened to the ends of the Strips 1 carries a Threaded Pin, which fits in the holes in the Flat Trunnions 3. By removing this Pin, the frame may be folded flat.






The Meccanitian consists of two  $2\frac{1}{2}$ " Strips 1 to the ends of which two  $5\frac{1}{2}$ " Strips 2, bent as shown, are bolted. The slot 3 should be passed over the top strip of the ladder, when the device will fall "head over heels" to the bottom.

#### Parts required:


Model No. 2.30 Baby Chair


8	of	No.	2	4	of	No.	35	
2		21	3	35	2.7	23	37	
2	,,,	21	5	2	,,,		37A	
6	,,	21	12	4	23	,,	38	
2	10	21	16	8	"	21	48A	
2	,,	21	17	4	,,	2)	90a	
4	12	100	22	1	,,	12	111c	

The Bolts 1 are all secured pivotally (see S.M. Nos. 262 and 263), and the height of the chair may be adjusted by fitting any hole in the Strip 2 over the shank of a Bolt that is secured in an Angle Bracket bolted to the Double Angle Strip 3.



#### Model No. 2.31 Square-topsail Schooner








Parts


required: 5 of No.

15<sub>A</sub>



#### Model No. 2.38 Sifter


The  $5\frac{1}{2}''$  Strip 1 is pivoted by a bolt and two nuts (S.M. 262) to the Bush Wheel and also to a Trunnion bolted to the under-surface of the Flanged Plate 2. The Rod carrying the Bush Wheel is journalled in one of the side girders and through a Double Bent Strip.




						D.		
				4				h
					N .			M
						2		ä
art	S				2.0		100	8
qu	ired	:				7	400	
	No.							d
	140.	1						
"	11	2 5 6A				14.		Ñ
,,	1)				A .			A
"	1)	O.A			and the second			
"	1)	8 10 15		S 1				×
"	2.7	10		M				S
3.5	2.3	15						y
12	2.9	15A						
,,	23	17		0 1	9 6			Ü
"	21	19в	ĺ	0 1	(A)			
"	27	20в			- 101		Ì	
,,	"	22 24 35				0 0		ã
23	11	24						
"	"	35						
,,,	"	37				7 1		
,,	"	37A		- 9				
"	"	38 44				7 1		
,,	1)	44		200	10	7 1		
,,	1)	48 A						
,,	,	52						
34	,	54	A			3 1		3
,,	,	99	(PP -					
23	, ,,	111c	4	- 3 -1	G (val)			
,,	, ,,	115			1.7			
	, ,,	126		-				

#### Model No. 2.40 Candy Puller

6	of	No.	2	3	of	No.	35
2	- ,,	,,	8	36	,,	,,	37
262224	,,	,,	12	4	,,		38
2	,,	,,	15	4	,,	10	48A
2	,,	,,	17	1	,,	,,	52
2	,,	,,	19B	2	,,	,,	54
4		22	22	2	,,	13	62
1	,,	,,	24	4	,,	1)	90A





Model No. 2.41 Carrier Tricycle

Each pedal of the tricycle consists of an Angle Bracket pivotally attached to a crank 1 by means of a Bolt and two Nuts (see S.M. No. 262). The cranks are secured to a 1½" Axle Rod carrying a 1" fast Pulley Wheel 2. A cord passes round this Pulley and around the 3" Pulley Wheel 3, which is spaced away from the 2½" Strips 4 by a 1" fast Pulley Wheel 5. The Double Bracket 6 (Fig. 2.41a) is attached pivotally to the lower framework by a Bolt and Lock-Nuts (S.M. 263).

_	arts	red	
	•	No.	. 2
12	,,	"	5
2	1)	,,	11
6	11	,,	12
1	11	,,,	16
1	32	,,	17
2	22	2)	18a
3	22	,,	19в
2	23	"	22
45	2.1	"	37
5	"	21	37A
8	32	23	48A
2	,,	2.5	52 62
3	23	,,	
2	,,	"	111c 126a
2	12	22	120A





FIG. 2.41A



The operating cord 1 is given a complete turn round the pair of  $\frac{3}{4}$ " Flanged Wheels 2. It is then led round the 1" Loose Pulley 3, over the 3" Pulley 4, then down and round the  $\frac{3}{4}$ " Flanged Wheels secured to the Crank Handle 5. The vane 6 is rotated by a cord which passes round a 1" fixed Pulley 7 secured to the shaft of the Flanged Wheels 2.

#### Model No. 2.43 Airship




#### Parts required:


4	of	No.	1	2	of	No.	11
3	,,	"	5	10	,,	23	12
3	,,	"	10	25	,,	,,	37
		3	of 1	Vo 4	84		

#### Model No. 2.44 Motor Van


The Axle Rod 1 is journalled in a  $2\frac{1}{2}'' \times \frac{1}{2}''$  Double Angle Strip 2. The latter is bolted to a Double Bent Strip that is pivoted to the Flanged Plate 3 by a bolt and two nuts. Steering is effected by a cord attached to the ends of the Double Angle Strip 2 and passed round a 1" Pulley Wheel fastened to the lower end of the steering Rod.

#### Parts required:






#### Model No. 2.45 Derrick



Bracket, to the centre hole of which is secured a Bolt 14 that is free to turn in the Flat Trunnion 15. The swivelling movement of the crane is carried out by turning the handle 1, which simultaneously winds and unwinds the ends of a cord passing round the 3" Pulley Wheel 2 (see Fig. 2.45A). The cord 12, which is tied to the Flat Bracket 3 at the head of the jib passes

over the 2" Rod 4, under a similar Rod 5, and between two vertical 2" Rods 6, which act as guides, and is finally wound on to the Crank Handle 7. Hence on operation

of the latter the jib is raised or lowered. The cord 8 also passes round the Rods 4, 5 and 6, and is wound on to the Rod 9. Operation of the handle 10 raises and lowers the hook. The cords 8 and 12 are prevented from unwinding by bandand-pulley brakes 16.





The handle 1 carries a 1" Pulley 2, which drives by means of a cord a similar Pulley on a 2" Rod 3 journalled in a Cranked Bent Strip bolted to the Sector Plate. Two Double Brackets 4 are secured together by a Bolt 5, the shank of which presses very tightly on the Rod 3. This locks the double Brackets in position, and they revolve with the Rod 3. The outer Double Bracket carries a 1½" Rod 6, the end of which lies between two Strips 7, arranged at a short distance apart from each other and bolted to two Flat Brackets. These are secured to a further Strip 8 bolted pivotally to a transverse Double Angle Strip. As the shaft 3 rotates, the Rod 6 slides between the Strips 7 and so rocks the Strip 8 to represent the shuttle.


The Bush Wheel 9 carries two Angle Brackets placed together in the form of a Double Bracket, with their elongated holes overlapping, and in such a position that an imaginary line drawn through their opposite round holes, would cross the centre of the Bush Wheel. A Flat Bracket is bolted to the inner Angle Bracket in a line with the crank handle and forms a lever which engages 1" Pulley 10 mounted on a vertical sliding Rod 11. This Rod is journalled in a Double Angle Strip bolted between the lower holes of the two flat Trunnions and is further supported by two ½" Reversed Angle Brackets secured to the Angle Strip. As the Bush Wheel rotates, the Flat Bracket imparts to the Rod 11 a movement corresponding to the action of the needle.

The outer Angle Bracket on the Bush Wheel strikes once in every revolution the end of a Double Angle Strip 12. This is pivotally mounted by a Bolt passed through its second hole from the Bush Wheel end to the centre hole of the Flat Trunnion on that side of the model. The resulting movement of the Strip 12 represents the apparatus that pays out the cotton from the reel.

#### Model No. 2.47 Anti-Aircraft Gun







126A

#### Model No. 2.49 Stamping Mill

similar Strip, representing the movable portion of the


plane, is attached by means of Flat Brackets.

#### Parts\_required:

2	of	No.	3	30	of	No.	37
2	,,	,,	6A	2	23	,,	37A
10	,,	,,	12	11	,,	,,	38
2	,,	,,	15	1	,,	,,	48
1	,,,	,,	15a	1	,,	,,,	52
1	,,	,,	17.	2	,,	"	54
2	,,,	,,	19в		11	,,	62
1	1)	**	20в	4	1)	"	90 A
4	,,	"	22	2	,,	,,	111c
1	,,	33	24	1	1)	"	115
1	,,	"	35	1	,,	" "	126


#### Model No. 2.50 Try-Your-Strength Machine

The Bush Wheel 1 is secured to a short Axle Rod 2, the lower end of which rests on a pair of Angle Brackets 3 bolted to the ends of four 51" Strips 4. The Strips 4 are pivoted as shown (Fig. 2.50A) on a  $1\frac{1}{2}$  Rod 5, and on their opposite ends rests a  $\frac{1}{2}$ loose Pulley Wheel 6. When the Bush Wheel 1 is struck, the 51 Strips fling the Pulley Wheel 6 upward, but the wheel is guided by the vertical 121/2" Strips 7. The weight of the Strips 4 then causes the Bush Wheel to resume its original position.




6	of	No.	1	2	of	No.	10
6	,,	,,	2	10	,,	,,	12
1	,,	,,	3 5	2	,,	21	18A
1 2 2 4	,,	,,,		1	,,	21	23
2	,,	,,	6A	1	,,	23	24
4	12	,,	8	3	,,	,,	35
				60	33	"	37
		4		6	22	"	37a
			1	4	11	12	38
1	ı	1	12	1	,,	"	45
ml.	1	7.		1	,,		48
ďΔ.	Æ	2 1	, '	1	> 1	12	48A
C e	Ε΄.	2.57	1	1	,,	12	52
, .				3 2 2	2.3	,,	54
v	Æ	1		3	2.7	"	90A
				2	,,	19	100
		Fig.	2.50в	-2	, ,	1)	126





#### Model No. 2.51 Roundabout



When the crank handle is turned, the drum 2 (formed by butting together two \(^3\)" Flanged Wheels) turns the 3" Pulley Wheel 3 by means of an endless cord. The 1" fast Pulley Wheel 4 similarly turns a second 3" Pulley Wheel 5 resting on another 3" Pulley Wheel 6 (see Fig. 2.51a). The end of the Axle Rod 7 is quite free to revolve in the boss of the lower 3" Pulley Wheel 6.

#### Model No. 2.52 Tipping Motor Wagon

				Pai	requ				
2	of	No.	1	4	of	No.	19в	1	of
1	71	,,,	2	4	,,	,,,	22	2	,,
1	,,	,,		1	,,	23	24	4	1)
2	,,	,,,	6a	6	,,	23	35	2	2.7
ó	,,	,,	12	59	,,,	,,	37	3	11
4	1)	,,	16	4	,,,	"	37A	1	1)
1	,,	23	17	1	,,	2.3	45	2	,,
1	,,	, ii	18A	1	,,	"	48	1	10
				7		23	48 A		

The front Axle Rod is journalled in a  $2\frac{1}{2}'' \times \frac{1}{2}''$  Double Angle Strip 1 which in turn is bolted to a Double Bent Strip 2. The Double Bent Strip is pivoted to the Sector Plate by a bolt and two nuts. Cord passing over a 1" Pulley Wheel attached to the Rod 3 is fastened to the ends of the Double Angle Strip 1, and by rotating another pulley, which represents the steering wheel, the road wheels are deflected.







Fig. 2.51A







#### HOW TO CONTINUE


This completes our examples of models that may be made with MECCANO Outfit No. 2. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 2A Accessory Outfit, the price of which may be obtained from any Meccano dealer.

#### Model No. 3.1 Drilling Machine

#### Model No. 3.2 Strip-Bending Machine

Model No. 3.3 Letter Balance

This model represents a device for bending bars or rods of metal to circular form, and may be put to practical purpose in shaping strips of tin or similar material. A loose Pulley 1 is spaced by a Collar and Washers in the centre of the short Rod 2 journalled in a 13" Strip 3. The latter is secured to the end of a 3" Bolt 4 and spaced away from the 3" Pulley 5 by means of a number of Washers. The opposite end of the Rod is supported by a  $5\frac{1}{2}$ " Strip 6. The Handle 7 is secured to a  $3\frac{1}{2}$ " Rod carrying a 1/2 Pinion 8. This engages with a 57-teeth Gear Wheel 9 mounted on another 31 Rod which is free to revolve in the boss of the Wheel 5. The Gear Wheel 9 carries a 3" Strip 10 forming one of the bearings for a short Rod carrying a second 1" loose Pulley 11. The latter is also spaced by means of a Collar and Washers so that it lies immediately above the groove of the Pulley Wheel 5. The material to be shaped is passed between the two loose Pulleys at the top of the Wheel 5, and on rotation of the handle 7 the arm 10 is caused to move downward so forcing the object to the same curvature as the circumference of the wheel.




NAME OF TAXABLE PARTY.		
Parts	required	:


				-		1					
2	of	No.	4	1	of	No.	19в	2	of	No.	
2	.,	,,	5	2	1 2	7.7	20в	4	,,	,,,	59
2	,,	,,	10	1	,,	,,	21	2	"	23	62
2	1 7	,,	11	4	,,	,,	22	1	27	,,	63
1	,,	,,	12	2	,,	"	22a	1	23	"	111
1	,,	,,	15	1	,,	"	24	1	,,	"	115
2	,,	,,	15A	3	,,	"	35	3	1,	,,,	125
2	,,	,,	17	21	,,	12	37	2	,,	>>	126a
				1	,,	,,	46				


Parts required:


4	of	No.	2	2	of	No.	18A	1	of	No.	53
2	,,	1)	3	2	,,	,,	20в	4	,,	,,	59
5	,,		5	2	17	,,,	22A	1	,,	- 00	62
2	,,	1)	10	4	,,	,,	35	1	,,	1,	63
1	,,	,,	11	37	,,	1,	37	2	,,	,,	90 A
4	,,	"	12	6	,,	1)	37A	2	,,	,,	111
2	,,	,,	12 <sub>A</sub>	2	,,,	12	48A	4	,,,	,,	111c
1	2.1	- 33	15	1	,,	12	<b>4</b> 8 <b>B</b>	2	,,	,,	125
2	,,	,,	17	1	,,	,,	52	2	22	,,	126A




connections at 12 are lock-nutted to allow free action.









#### Model No. 3.18 Tower Wagon




#### Model No. 3.19 Pile Driver




#### Model No. 3.20 Actuated See-Saw



The model is actuated by the motion of one pair of travelling wheels. The axle to which these wheels are secured carries two 1" fast Pulley Wheels, which are connected by endless cords to similar Pulleys on the same Rod as a  $\frac{1}{2}$ " Pinion Wheel. This  $\frac{1}{2}$ " Pinion meshes with a 57-teeth Gear Wheel secured to the Rod of a Bush Wheel, and the latter is connected by means of a  $5\frac{1}{2}$ " Strip to an extended crank (a  $2\frac{1}{3}$ " Strip and a Crank bolted together) secured to the pivotal Rod of the see-saw.




#### Model No. 3.22 Hand Trolley




#### Parts required:

4	of	No.	2	1	of	No.	18a	1	of	No.	45
3	23	33	3	4	,,	2.3	19в	1	,,	,,,	48в
2	23	**	5	2	,,	n	22	2	,,,	12	52
4	,,	22	8	1	,,	12	24	3	1,	"	59
8	,,	,,	10	1	,,	12	26	4	,,	,,	90A
4	,,	22	11	1	12	,,	27 A	2	,,	,,	125
2	13	,,	15a	6	,,	: 0	35	2	12	2.3	126a
4	12	22	16	40	,,	17	37				


The connecting arm is pivoted at its lower end to the Bush Wheel and at its upper end to the hand lever, a bolt and two nuts being used to pivot the arm in each case. The drive is transmitted to a 1" Pulley Wheel on the axle of the road wheels by means of a crossed belt passing round another 1" Pulley that is secured to a Rod connected via a 3:1 gear ratio to the 1½" Rod carrying the Bush Wheel. This Rod is journalled in a 3½" Strip fastened to the side Angle Girder, and also in a Double Bent Strip secured to the inside of the Girder.



The animal rocks about a short Rod secured between the rocker-frame which does duty as "legs." This frame consists of two  $3\frac{1}{2}$ " Strips 3 bolted at their upper ends to cranks in which the short Rod is secured, and at their lower ends to two  $2\frac{1}{2}$ " large radius Curved Strips 4, which are



#### Model No. 3.25 Fire Escape



The moving portion of the escape slides on the 12½" Angle Girders 4 of the fixed ladder and is guided by two ½" Reversed Angle Brackets 5. The cord for extending the ladder passes over the ½" loose Pulley 1 and is wound on the

Crank Handle 2. The Pulley 1 revolves freely on a  $\frac{3}{4}$ " Bolt that is secured by two nuts to an Angle Bracket bolted to the  $3\frac{1}{4}$ " Strip

Angle Bracket bolted to the  $3\frac{1}{2}$ " Strip.

A 3" Strip, weighted with a  $\frac{3}{4}$ " Flanged Wheel 6 to form a brake lever, is pivoted by a  $\frac{3}{8}$ " Bolt to the  $5\frac{1}{2}$ " Strip 7, and a piece of cord is passed round the 1" Pulley 3 on the hoisting shaft, and tied to the Strip. The pressure of the weighted lever is sufficient to keep the ladder raised in any position.


#### Model No. 3.26 Auto Swing Boat

The connecting Strip 1 is attached pivotally at one end to a Threaded Pin secured to the Bush Wheel 2 on the driving spindle of the motor, and at the other end by means of Bolt and Lock-Nuts to a Crank 3 mounted on the shaft 4, which operates the swing boat.

#### Parts required:

3	of	No.	1	1	of	No.	10	86	of	No.	37	2	of	No.	90A
16	,,	1)	2	12	1)	22	12	2	23	,,,	37A	2	2.1	,,	99
6	,,,	12	3	2	12	22	15	1	21	,,	59	2	2.1	,,	100
		"	5	1	13	22	24	2	23	11	62	1	2)	12	111c
8	,,	,, "	8	2	11	,,	35	1	,,	12	63	1	23	12	115
						2	of ]	No.	12	6A					

Clockwork Motor (not included in Outfit)



#### Model No. 3.27 Scales

Parts required:

		1 4	165 16	qui	icu	•	
10	of	No.	2	2	of	No.	48A
1	1)	,,	3	1	22	2.5	48в
2 5	,,	- 55	5	2	,,	1)	52
5	21	12	- 8	1	,,	,,	53
7 5 2 4	,,	,,	10	2	,,	"	54
5	,,	13	12		,,	23	59
2	,,	11	15A	2	,,	23	62
	,,	"	19в	2	,,	,,	100
67	,,	23	37	2 2 2 2	1)	,,	126
2	,,	23	38	2	,,	,,,	126a


#### Model No. 3.28 Lawn Marker

The small roller, which consists of two 3" Flanged Wheels secured to a short Rod, rests on the edges of the two 3" Pulley Wheels. In actual practice the container is filled with whitewash, in which the inner wheel is partially immersed, and the mixture is transferred via the roller to the outer wheel, which does the actual marking.


Parts


#### Model No. 3.29 Hand Car

Model No. 3.30 Two-Cylinder Vertical Steam Engine



The hand levers 1 are each pivotally attached to the car by a bolt and two nuts (see Standard Mechanism No. 262) and are connected in a similar manner to two further levers, one of which, seen at 3, is pivoted to a Bush Wheel 4 whilst the other, on the further side of the model, is pivoted to a Coupling, which serves as a crank in the same way as the Bush Wheel 4. Both Bush Wheel and Coupling are secured to the Rod carrying the Gear Wheel 5, and motion is thus transmitted to the rear wheels. The steering foot lever 6 is secured by a Crank to a short vertical Rod which, in turn, is secured by another Crank to the Double Angle Strip carrying the front axle.





113

These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A)



#### Parts required:

2	of	No.	1	6	of	No.	8	2	of	No.	22	12	of	No.	45
17		12	2	8			12	2			22A	4			90 4
2		221	4	2			17	64			37	2			99
2	"	32	5	2	**	1)	19в	2	1)	1,	37A	2	,,	.,	100
												2	12	,,	111c


#### Model No. 3.36 Horse Sleigh

#### Parts required:


3	of	No.	2.1	13	of	No.	37 48a	1	of	No.	57
4	"	,,,	5	1	22	,,	48A	2	- 11		90
1	,,	,,	23	1	,,	.,	52	1			126A



#### Model No. 3.37 Pit Head Gear



Frg. 3.38A



			1				1	2	of	No.	20в	1	of	No.	48				
2	of	No.	1	12	of	No.	11	1	,,	,,	22	1	,,	23	48A	3	of	No.	90A
		,,	2			73	12			,,,	24	2	,,		48в	1	,,	,,	98
3	,,	3)	3				12A			1)	35			22	52	2	,,	,,	111c
		,,,	5	2	,,	,,,	15	60		,,	37			,,	53	4	,,	,,	125
1	,,	,,	6A	1	,,	,,,	15A	1	,,	,,	37A	2	23	,,,	54	2	,,	,,	126
2			8	4		12	19в			,,	38	4	**	**	59	1			162

It should be noted that the steering cord is given a complete turn around the two  $\frac{3}{4}''$  Flanged Wheels 1 to prevent slipping. The steering column 2 is journalled in the end of a  $1\frac{1}{2}''$  Strip, the other end of which is bolted to a  $2\frac{1}{2}'' \times \frac{1}{2}''$ 

Double Angle Strip secured between the two Sector Plates 3. The front road wheels are secured to a 5" Rod that is journalled in the end holes of a 3½" × ½" Double Angle Strip. The ends of the steering cord are tied to this Strip, which is pivoted by means of a Bolt and Lock-nuts (S.M. 263) to the central hole of a 1½" × ½" Double Angle Strip.

means of a Bolt and Lock-nuts (S.M. 263) to the central hole of a  $1\frac{1}{2}'' \times \frac{1}{2}'''$  Double Angle Strip. The latter is bolted between a pair of Trunnions attached to the underside of the  $5\frac{1}{2}'' \times 2\frac{1}{2}''$  Flanged Plate. The tank 4 merely rests on the  $5\frac{1}{2}''$  Strips 5.



Model No. 3.39 Coffee	Grinder
Parts required:  2 of No. 2   1 of No. 27A 6 ,, 3   16 ,, 37 2 ,, 4   2 ,, 54 2 ,, 16   3 ,, 59 1 ,, 19B   1 ,, 115 1 ,, 26   4 ,, 125	
	Model No. 3.40 Land Yacht Parts
	required:  1 of No. 1  1 " " 3  4 " " 8  1 " " 10  1 " " 13
	3 , , , 16

#### Model No. 3.41 Fire Truck

The front axle is journalled in a  $2\frac{1}{2}''$  Double Angle Strip that is pivoted through its centre hole to a Double Bent Strip secured to the Flanged Plate 15. Steering is effected from the Pulley 13 secured on a 3½" Rod that is passed through the 3½" × 2½" Flanged Plate 16, and held in position by Collars. On the lower end of the Rod is a Bush Wheel 14, which is connected to the pivoted Double Angle Strip by cords tied to opposite holes in the Bush Wheel and to the ends of the Double Angle Strip.

The lower part of the escape is mounted pivotally on Bolts 10 passed through the upturned ends of a  $2\frac{1}{2}$ " × 1" Double Angle Strip that is bolted to a 3\frac{1}{2}" \times \frac{1}{2}" Double Angle Strip which, in turn, is supported on two vertical 2\frac{1}{6}" \times \frac{1}{6}" Double Angle Strips. The upper or moving portion of the escape slides between the 121" Angle Girders 9 and is held freely in position by the Nuts of the Bolts 11.


The ladder is extended from the Crank Handle 2 (Fig. 3.41A) that is journalled in a 2\frac{1}{2}" \times \frac{1}{2}" Double Angle Strip bolted to a 51" Strip that, in turn, is bolted across the flanges of the Sector Plates. A Cord 7 is wound on to the Crank Handle and one of its ends is tied to a 21 Strip that spans the inner end of the 12%" Strips forming the sides of the extending ladder.

FIG. 3.41 A

Its other end 7A is then led towards the outer end of the fixed ladder, round a law loose Pulley held on a bolt in the centre hole of a  $2\frac{1}{2}$ " Double Angle Strip that spans the outer ends of the  $12\frac{1}{2}$ " Girders 9, and finally is tied to the same 21" Strip to

which the end 7 is already attached. Thus by turning the Handle 2 the escape is pulled inward or outward. The Crank Handle 1 carries a 1" Pinion 3 that engages a 57-teeth Gear 4 secured to a Rod 12. A Cord 8 is wound a few turns round the Rod 12 and is then led to the 21/2" Strip 5 where it is secured. By turning the Crank Handle

> On turning the Handle in the opposite direction, the escape is lowered by its own weight.



of	No.	1	3	of	No.	20B	2	of	No.	48B
,,	"	2	1	11	"	21	2	,,	,,,	52
,,	**	3	2	,,	,,	22	2 2 2	,,	,,	53
22	22	5	1	,,	"	23	2	,,	22	54
27	22	8	1	"	22	24	4	22	22	59
22	22	11.	1	22	22	26	1	22	22	63
11	23	12	1	22	"	27A	2	55	**	90a
,,	"	12A	4	22	33	35	2	33	11	99
,,,	,,	15	87	11	,,	37	2	55	,,	100
"	"	15A	8	"	11	37A	4	22	>>	111c
,,	"	16	10	"	"	38	2	"	25	126A
27	,,	18A	2	"	27	40	1	>>	"	162A
22	22	19	1	22	22	45	1	,,	22	162B
22	22	19s	1	22	22	46	1	"	**	165
,,	**	19в	8	22	22	48A				


Model No. 3.42 Farm Tractor

The seat (a 11" Pulley) is secured on a Threaded Pingand attached to a pair of 21" Curved Strips. The latter are secured to two 51" Strips fixed in the bottom row of holes of the Motor Plates. A 21 "Strip is pivoted to the Motor reversing lever by means of a Reversed Angle Bracket, and is supported by a 11 Strip which is attached pivotally to the Motor.

#### Parts required:

2 of No. 2   4 of No. 11 5 " " 5   5 " " 12 1 " " 6A   1 " " 15 2 " " 10   2 " " 16	1 of No. 17 2 , , , 19 <sub>B</sub> 1 , , , 32 2 , , , 20 <sub>A</sub> 28 , , , 37 1 , , , 21 1 , , , 22 5 , , , 38 1 , , , 24 1 , , , 48 <sub>A</sub>
3000	1 " 24 1 " " 48A 2 " " 26 2 " " 59 1 " 63 4 " " 90A 2 " " 111 1 " " 111c 1 " " 115
	1 "," 125 Clockwork Motor (not included in Outfit)

Model No. 3.44 Flax Cleaner



Two pairs of 5½" Strips are connected loosely towards their centres by means of nuts and bolts 1. The punch 2 consists of a 13" Rod secured in the boss of a Crank 3, which is bolted to a Double Bracket secured at 4. A Spring 5 serves to open the handles after the punch


has been used; it is placed on the Rod 2 and held in position by means of a Collar 6, while its other end is attached to a &" Bolt 7 passed through

one pair of  $5\frac{1}{2}$ " Strips. After passing through the paper the punch enters the

end hole of a 3" Strip 8. The latter is bolted at 9 to a Double Bracket, while its other end passes beneath a similar bracket at 10.

#### Parts required:

[4]	of	No.	2	14	of	No.	12	1	of	No.	59
1	,,	,,	5	1	21	23	18A	1	21	2.2	62
12	23	13	64	21	12	,,,	37	2	23	11	90
4	17	"	11	3	"	,,	37A	1	*1	2.5	111c




#### Model No. 3.45 Railway Wagon Swivel Crane

The flanges of the Sector Plates 1 are bolted to the 3" Pulley Wheel 2 upon which the crane swivels, and the spindle of the Pulley Wheel is rotated by the Worm 3 engaging the Gear Wheel 4 (Fig. 3.45A). In order to bring the Worm centrally over the teeth of the Gear Wheel 4, Washers are placed beneath the Angle Brackets 5 in which the spindle of the Worm is journalled.

#### Parts required:

4	of	No.	1	1	of	No.	27A	
6	- 12	21	2	1	12	,,	32	
1	,,	>>		3	23	22	35	
2	,,	+3	5	70	,,	,,	37	
4	,,	**	8	2	,,	,,	38	
3	12	**	11	2	**	,,	48A	
4	12	.,,	12	2 2		"	52	
2	,,	1)	15	2	,.	,,	53	
1	,,	**	15A	2	2 8	.,	54	
2	,,		17	1	21	,,	57	
1	**	12	19	. 3	21	,,	59	
1	,,	3.7	19в	1	,,	,,	63	
4	23	10	20в	1	,,		115	
4	21	,,	22	4	,,	,,	125	
1	,,	11	22A	2 2	,,		126	
1	,,	13	24	2	,,	17	126a	



The six 3½" Strips forming the rotating frame are

Parts required:

fastened to a Bush Wheel that in turn is attached to the Rod 1. The  $3\frac{1}{2}$  Strips are braced by six  $2\frac{1}{2}$  Strips.

The drive is transmitted from the operating shaft by

means of endless cords. Two separate cords are used

in order to secure a more positive drive.


#### Model No. 3.46 Newton's Disc

This model demonstrates that the colours of the spectrum, which are most simply produced by directing a ray of white light through a prism, can be re-combined to form white light. The cardboard disc is divided into equal sectors, and the seven colours of the spectrum—red, orange, yellow, green, blue, indigo, and violet—are

painted on separate sectors. If the disc is rotated at a high speed by means of the hand wheel and the gears shown, the disc appears to be of a greyish-white colour.



2	of	No.	15	10	of	No.	37
1	,,		19в	1	23	,,	38
1	,,	,,	24	2	,,	,,	52
1	,,	"	26	2	,,	,,,	53
1	,,	**	27 A	2	"	,,	59
		1	of N	0. 1	15		



Model No. 3.47
Vertical Steam Engine

2	of	No.	12	2	of	No.	38
1	,,	,,	16	1	,,,	,,	45
1		210	17	1	,,	23	52
1	1)	11	19в	1	. 21	11	59
1 2 3	,,	,,	20B	1	,,	,,	115
3	12	1)	22	1	32		162
1	,,	,,	24	1	12		163
9	"	,,	37	1	,,	2.5	164

Parts required:

3 of No. 3

10 , , , 5

2 , , , 8

1 , , , 10

2 , , , 11

44 of No. 37

2 , , , 11

4 , , 12

2 , , , 15A

1 , , , 16

2 , , , 16

2 , , , 18

1 , , , 17

1 , , , 18

1 , , , 17

1 , , , 18

1 , , , 17

1 , , , 18

1 , , , 17

1 , , , 18

1 , , , 19

1 , , , 59

2 , , , 19

1 , , , 59

1 , , , 62

1 , , , 21

1 , , , 90

2 , , , 19B

1 , , , 62


1 , , , 21

1 , , , 111c


1 , , , 24

1 , , , 115

The arrangement of the treadle is shown in detail in Fig. 3.48A. The Crank 1 is provided with a Flat Bracket, the round hole of which coincides with the elongated hole of the Crank, and receives the short Rod 2. The Crank 1 is free to turn about a Threaded Pin 3, secured to the 3" Pulley Wheel 4, and once the latter is set in motion it can be kept in rotation by working the treadle 5. The Strips 6 of the saddle (Fig. 3.48) are duplicated and their ends form slots to receive the flanges of the Angle Girders 7. The hand wheel 8 is a dummy one, but if desired it may be arranged to operate the saddle by an endless rope device.




#### Model No. 3.49 Car Lifting Apparatus



Four  $5\frac{1}{2}''$  Strips 1 are attached pivotally by lock-nutted bolts to the  $12\frac{1}{2}''$  Angle Girders, which form the base of the model, and to the carrier 2, which receives the car. The Crank Handle 3 carries a  $\frac{1}{2}''$  Pinion meshing with a 57-teeth Gear on the Rod 3 which forms a drum for a length of cord attached to the carrier. The Rod runs freely in the transverse hole of a Coupling 6 that is secured to the upright Strip by a  $\frac{3}{8}''$  Bolt. A Threaded Pin carries the 1" Pulley 7 and its shank is inserted in the tapped hole of the Coupling, so that when the Pulley is rotated clockwise the Pin nips the Rod. The carrier 2 is returned to its original position by a length of elastic or Spring Cord 8.

#### Model No. 3.50 Pastry Designer




#### Model No. 3.51 Drop the Nigger

The Sector Plate 1 is a target, which, when hit, allows the nigger to be dropped. The Plate 1 is carried on the Strip 2 pivoted at 3, and the weight of the nigger supported on another Sector Plate 4 pivoted at 5 by means of the cord 6 keeps the lower end of the Strip 2 hard against a short Rod 7 pivoted at 8. When the target is hit and knocked back the Rod 7 is released and falls about its pivot, allowing the Sector Plate 4 with the nigger to drop.


Parts
required:

1 of No. 1
6 , , , 3
8 , , 8
1 , , 12
3 , , 15A
2 , , 15A
2 , , 15A
2 , , 35
33 , , 37
1 , , 44
4 , , 48A
4 , , 48A
2 , , 53
2 , , 54
3 , , 59
1 , , 63

# Parts required: 2 of No. 2 3 ,, 5 3 ,, 11 1 ,, 22A 1 ,, 27A 9 ,, 37




#### Model No. 3.52 Roundabout



#### Model No. 3.53 Swing Boat

Parts required:

2	of	No.	1	6	of I	Vo.	37A
18	,,	23	2	8	"	,,	38
6	,,	11	3 5	1	,,	,,	45
4	,,	,,	5	3	,,,	,,	48A
8 3	,,	,,	8 .	1	,,	,,	52
	,,	,,	12	4	,,	,,	59
1	,,	11	15	2	,,	,,	62
1	,,	**	15A	1	,,	,,	63
	,,	"	16	1	23	,,,	98
1	,,	"	22	2	,,	,,	99
10	,,	,,	35		,,	,,	100
68	,,	,,	37	4	,,	,,	111c




#### Model No. 3.54 Flex Making Machine

The two wires to be twisted are fixed at one end of the machine to a Hook 1 which is attached by an End Bearing to the Crank Handle. At the other end the wires are looped over two Threaded Pins fixed by Collars to the spring controlled Rods 2. The  $3\frac{1}{2}'' \times 2\frac{1}{2}''$  Flanged Plate 3 carrying a  $3\frac{1}{2}''$  Rod is free to slide in the built-up channel girders, and as the Crank Handle is turned it is pushed ahead of the twisting wires, so keeping the finished flex even. As the wires shorten through twisting, the Rods 2 slide longitudinally, extending the Spring.


#### Parts required:

		1	arts	requ	irec	1:	
3	of	No.	5	1	of	No.	19s
1	,,	23	6A	2	,,	,,	35
4	,,	,,	8	.32	,,	,,	37
4	,,	,,	12	2	,,	,,	38
2	,,	,,	15A	1	,,	"	43
1	,,	,,	16	1	,,	,,	45
Ĉ=		- 0	4	2 2 3	,,	"	48A
	1	1	7	2	22	"	52
8	V =			3	22	23	53
L				1	,,	2.3	57
-	green)		रहा ।	3 2	,,	,,	59
I				2	,,	,,	115
				1	,,	,,	166
Size.	-	Commercial	\$335-1				


	art										
re	qui	ired:						36	of	No.	37
4	of	No.	1	2	of	No.	19в	8	,,	,,	48A
12	,,	33	2	4	,,	,,	22	2	,,	,,	52
2	23	1)	8	1	,,	23	24	3	,,	,,	53
8	,,	,,,	12	2	,,	,,	26	2	,,,	,,	59
1	,,	,,	15	1	,,	,,	27 A	1	,,	,,	63
3	,,	,,	15A	1	,,	,,	32	1	,,	"	115
1	,,	"	16	2	,,	"	35	2	,,	"	126A



#### Model No. 3.55 Railway Breakdown Crane



#### Model No. 3.56 Paddle Steamer



							Parts	requ	iire	d:					
6	of	No.	2	4	of	No.	19в	1	of	No.	45	4	of	No.	90A
6	1,0	,,	3	2	- 22	**	20A	1	,,	,,	46	2	,,	21	99
	,,	23	4	4	3)		20B	10	2.1		48A	2	,,	,,	100
10	,,	,,	5	1	11	,,,	21	1	21		48в	2	21	23	111
5	,,,	,,,	10	1	11	,,,	22	2	23	11	52	1	21	11	115
4	22	21	11	1	33	31	22a	2	,,	12	53	1	,,	,,	116A
14	31	23	12	1	,,,	23	24	1	23	12	54	2	,,	2.1	125
1	,,		13	6	,,	- 21	35	4	23		59	2	"	,,	163
1 2 4 2	23	1)	15A	93	,,	>1	37	1	2.5	11	62	1	,,	,,	165
4	,,	,,	16	4	,,	23	37,	1	23	,,	63				
2	,,	1)	17	14	,,	,,	38								
1			18A	1		0000	40								

Fig. 3.56B


The 3" Pulley Wheels forming the paddles are attached to  $3\frac{1}{2}$ " Rods, to the inner ends of which 2" Pulleys are fixed (Fig. 3.56a), and the 2" Pulleys are connected together rigidly by a  $\frac{3}{4}$ " Bolt 1 that is locked in position by nuts. The Bolt 1 forms also a pivot for two small Fork Pieces (one of which is taken from a Swivel Bearing) to which the piston rods of the oscillating cylinders are fixed. The cylinders pivot about  $4\frac{1}{2}$ " Rods, one cylinder being mounted on a  $3\frac{1}{2}$ "  $2\frac{1}{2}$ " Double Angle Strip while the other is attached rigidly to a Collar 4 by a bolt on which are placed two Washers. The Collar is secured, of course, to the Rod.

The funnel is built up of eight  $2\frac{1}{2}$  Strips and eight  $2\frac{1}{2}$  Double Angle Strips, which are attached at the top to a  $1\frac{1}{2}$  Pulley and at the bottom to a Bush Wheel. It is attached to the hull by the lower hole of the Double Bracket 2, Fig. 3.568. The top hole of this Double Bracket forms a support for the lower end of the escape pipe.


The bridge consists of a  $2\frac{1}{2}$ "×1" Double Angle Strip and two  $2\frac{1}{2}$ "× $\frac{1}{2}$ " Double Angle Strips, and the complete assembly is bolted to a Double Bent Strip. The latter is attached to a transverse  $2\frac{1}{2}$ " Strip. The bolt holding the bridge to the

bolt holding the bridge to the  $2\frac{1}{2}$ " Strip serves also to retain a Crank in which the foot of the mast is secured.

The steering wheel 5 consists of a 1" fast Pulley mounted by its set-screw hole on the end of a \(^34\)" Bolt that is secured to the floor of the bridge. The binnacle is merely a Threaded Pin on which is fixed a Collar.



#### Model No. 3.57 Kinetograph




Most Meccano boys probably are aware of the principles of the Kinetograph, but for the benefit of those who have not seen one in action, we may mention that it is a device which imparts an appearance of animation to a series of pictures, each differing slightly from the other and passed in rapid succession before the eyes. In this respect it resembles the remarkable principle upon which the modern cinematograph is based.

In constructing the Meccano model the following details will prove useful:—The drum consists of a  $12\frac{1}{2}''$  Strip bent to form a circle, with its ends overlapping one hole, and bolted to eight vertical  $5\frac{1}{2}''$  Strips forming the sides. Two pairs of opposite  $5\frac{1}{2}''$  Strips are connected by  $3\frac{1}{2}''$  Strips and Angle Brackets bolted in the third holes from their lower ends. The  $3\frac{1}{2}''$  Strips cross at right angles to one another and are bolted in the centre to a Bush Wheel, in the boss of which is secured a short Rod forming the pivot of the revolving drum. This Rod is journalled in a Double Bent Strip bolted to a  $2\frac{1}{2}'' \times 1''$  Double Angle Strip 2. This, in turn, is secured to the base of the model by two  $1'' \times 1''$  Angle Brackets 3. A further bearing for the short Rod consists of a Crank bolted to the base of the model.

The drum is rotated from the Crank Handle 4, on which is mounted a ½" Pinion engaging a 57-teeth Gear Wheel 5 secured to a 3½" Rod carrying a Pulley Wheel 6. The latter is connected by means of a cord 7 to a similar wheel nipped to the vertical spindle of the drum. Bearings are provided for the inner ends of the Crank Handle and 3½" Rod by a Double Angle Strip bolted between the Plate 8 and 5½" Strip 9. The sighting box 10 is built up from a framework of Strips and is secured by means of a Crank 11 to a short vertical Rod rigidly mounted in the boss of the 1½" Pulley 12. The four sides of the framework 10 are covered with some black material; stiff black paper suitable for this purpose may be obtained from any stationers. The drum is enclosed in the same way, but the covering paper should be cut in a strip measuring 12½"×4½" and pierced with slots spaced 1½" apart (from centre to centre) so that they fall exactly between the upright 5½" Strips. The slots should measure 1½"×½".

The type of drawing suitable for use in this model is shown in Fig. 3.57A, and the dimensions indicated therein should be followed carefully. No doubt Meccano boys will be able to devise numerous amusing pictures of a similar kind for themselves. The strip of stout white paper carrying the sketches is inserted in the bottom of the drum, as indicated at 13. The model is now ready for operation. Placing the frame 10 over the eyes, the line of vision is directed through the narrow end, where the Strips are held apart by means of Double Brackets, and through the slots in the drum. The latter should be rotated rapidly by operating the handle 4, and as it revolves, the little dog shown in Fig. 3.57A will be seen imming over the fence, with a most realistic and amusing action.

		Jumping Over the renee with a most reason	
	Parts required:	1 <del>7</del> "	
1 of No. 17 " " 6 " " " 1 " " " 3 " " " 4 " " "	1   1 of No. 15A 2   2 ,, , 16 3   1 ,, , 19s 4   1 ,, , 21 5   2 ,, , 22 8   1 ,, , 24	12 of No. 38 1	
2 ,, ,,	11   1 ,, ,, 26	4 ,, , 59 \	
12 "	12   1 ,, ,, 27A	2 ,, ,, 62	
2 ,, ,,	12a   60 ,, ,, 37	Fig. 3.57%	· · · · · · · · · · · · · · · · · · ·



#### HOW TO CONTINUE

This completes our examples of models that may be made with MECCANO Outfit No. 3. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 3A Accessory Outfit, the price of which may be obtained from any Meccano dealer.

6.4	8 01	27	00	1 8	77	40	0	1 :	12	9	1	6	9	9	13	ı,	3	-	CI		7	4	28	-	-			_	,	_	1			_	3,	rto	rto	-	1	1	1	_		_	C1 .	•	_ `	4 00	_			-	61	_	4 (			-		64	4	_	1	12	-	1 8	280		164	
9	000	28	4	24	77	000	;	14	1	1	26	00	2	18	2	64	1	9	1	4	16	00	48	9	4	07	_	+ 0	0 '	4 (	9	1	7	21	S	4	2	8	_	4	4	00	4	4	61	· 0	4 4	* -	4 10	0 01	-	ıc	1	01 0	n	1 9	4 0	1	-	- 1	1	2	2	24	-	-	314	9		36
ŠA	14	x 01		12	4	8	9 0	00	1	1	12	4	1	14	2	61	1	io	!	4	4	1	12	1	4	-		0 0	3	1	_	24	4	27	4	1	27	24	1	1	1	4	1	1	1	27 -	1	1	6	0 01	-	2	1	01	_	1	1		1	1	1	1	1	3	1	1	143	1		19
c	16	26.	4	12	00 0	90	+ 0	9	1	1	14	4	23	4	1	.1	1	-	1	İ	12	00	36	9	-	6	-	. 0	ο.	+ 1	c	0	n	1	io	4	1	1	-	4	4	4	4	4	2	4 0	0 0	0 -	1 0	4	1	8	1	1 '	21	1	- 0	1	1	-	1	2	51	19	-	-	169	9		24
44	9	2 10	63	9	24 9	2	ŧ,	4	1	1	ıc	4	61	1	1	-	1	-	1	-	œ.	0	+	1	1	1			1	1	1	1	n	1	1	1		1	1	4	1	1	1	b	-			1			1	-	1	1		1			1	-	1	1	1	1	1	1	43	1		1
4	10	21	7	9	9	2	1 0	7	1	1	6	1	1	4	1		1	4	1	-	5	w	22	9	1	6	-	. 0	ο.	4 1	0	0	1	١	ıc	4	1	-	-	I	4	4	4	+		4 0	200	o -	- 0	4	1	01	1	1	61	١.	- c	4		1	1	2	<b>?</b> 1	19	-	1	126	9		0.4
3A	11	8	61	1	+ (	2	1	1	1	1	-	1	1	+	- 1	-	-	i	1	1	-	_	00	2	1	-	-	- 0	0 :	27 :	01	~	I	1	33	1	1	1	1		1	4	¢1	1	I	١.	- c	SI =	-	-	1	Ţ	ŀ	1	-	1 .	- c	4			1	-	н	w	1	-	32	1		9
8	10	18	1.	9	7	2	:	21	1	ī	00	1	1	1	1		1	1	1	1	œ	4	14	4	1	-	•		5	7	n	4	1	I	7	7	1	ı	-		4	-	63	4	_	+ 0	N -	- 1	-	-	1	Ø	1	1	_	1				-	1	Г	П	14	1	1	6	9	•	1.4
2A	1.1	1 4	1	4	21	1	1	Ī	I	1	4	1	1	1	1	-	1	1	-	1	1	1	C/I	2	1	1			1-		21	1	ı	f	1	1	1	1	1	1	1	ī	61	I	-	1					1	61	1	1	_	ı			-	1	1	г	ī	I	Ī	1	34	1		1
61	01	1 4	1	01	1	7	0	21	1	i	4	1	1	-1	1	- 1	1	1	1	1	.00	4	12	2		-			"	01	_	4	1	1	01	4	1	П	г	1	4	ī	1	4	1	4 0	η -	-	-	٠	1	1	1	1	1	1			1	1	1	Ī	-	14	-	1	09	9	-	14
ΙΛ	9	1 9	1	-	1 9	n		7	1	1	4	1	1	1	1	-	1	1	1	1	c.	0	1 4	67		-		1	1 0	01	_	_	T	Ī	1	7	1	_	1	ī	ī	1	1	4	1	10	N	1			1	ī	1	1	Ī	1	ı		1	1	1	1	ī	9	1	1	54	ī		y
-	4	1 00	1	1	1 (	77		1	Ť	-	-	1	1	1	ï	1	1	1		1	ur.	63	00	1	1	1			1	1	1	n	î.	1	7	2	1	1	-	1	4	i	ī	-	1	4.	1 -	- 1	-	- 1	1	i i	1	1	1	ľ	ı		-1	-	1	ī	-	00		1	36	9		0
	4	1 =	1	-	1		1	1	1	1	-	i	1	1	-	- 1	1	1	-	1	_	-	1	-	-	-	- 1	_	1	1	1	_	1	1	1	2	1	1	-	1	4	1	ľ	F	1	1	1	i i			-	T.	81	1	-	<u></u>	1			-	1	-	1	2	1	_	20	1		0
0A	- 1	'	1	_	1		1		d V	1	1	1	1	1	- 1	1		1	- 1	1	-	. 2	1	1	-	-		_	1	F	1	01	1	ī	7	1	1	1	-	1	1	-	1	1	1	' <del>'</del>	1 -	_		- 1	1	-		1	-	i.	te s			1	1	1	-	9	-	1		9		
0		4	1	1	1	,,			-	k	1		1	-1	- 1	-	-	1	- 1	- 1	_			1	-	_		_	<u> </u>	-	1	1	-	1	-	-	1	-	E	1	1	1	-	-	-	_						-	_	-	1	1	-	_		- 1	-	-	_	~1		1.0	-	cı	-	
00a	11	1 !	1	1	1 3	n 		1	  -	1	I.	1	1		_		1	1	- 1	- 1	-	-	-	- 1			-	_			1	_	<u>!</u>			1	1	-	1	1	1	1	-	-	1	1			_	- 1		1		!		1				- 1	- 1	-	1	_	-	1	-	_		-
8	11	4	1	1	1	٥.	<u>ا</u>	1		1	1	1	1	-			1	1	1		4		00						1		1		1			1	1	1	-	1	1	1	1		1					. 1			1	1	1	!					1	1		4	-	1	16	4		
	1 1	1 1	1	:	i	:	:	:	8	:	:	:	:													:	:	:			:	:	:	:		:		:		:		:	:	:	:	:			:			•			:	:	•		:				:		•	:		:		
	1 1	: :	:	:				:		:	:		:		:	:				: :						:	:	:	:	:	:	:	:	:		1 1	:	:	:	:	:	:	:		:	:	:	:	:			:	:	- 0	:	:	:	:	:			:	:	:	:	:	:	:		
	11			i				:	:	:	:	:	:		:	:				: :						:	:		:		:	:	:	:		:		:		:	:	:	:		:	:	:	:	:	: :	:	•	:	:	:	:	:	:	:				:		:		:	:		
PART.	4				:	:				:	:	:	-		:				:							:	:		•	:	į	:	8	:		•	:	:		:			:				:	:	: .	wide:	:	:				latu.	:						:		:		•	:		
0				:	:	:	:	:			:					:								:		•			:	ii ii	9	:		:	:	:		£ .	-	:	,	:	:		8	8	7	•	٠		***	4	-101 F		:	3§, c	9	:	:		. h		:	:	:	٠		:		
DESCRIPTION	121"	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	,	35"	3"	101 2		101	:		:	:	3		:	:								×	:	**	:		:	:		:	:	:	:	:	:	shaf		:			:		•	(fast)	" (loose)	1, 1,	(last)	diam		1	1	teeth			- 2	·	:		3-teet	:	:	:	:	cial)	32"	:		
CRIP	ps, 12								2+13"	183"	124"	186	73."	10	41,1	3 :	3	9.1%	1 0	1,4	o1 •	. 4	1 1	1,1	-	111"		. "			-\c1	32.7	- In			13"		(5,	(31	:	.3"	ls, 14	.2"	ls, 3"	-101	1		101 -	-(D4	. 60-	+ 1014	- c1	r-los		1070	£ .	els, l				1", 38	:	:	:		eds)	8, 7/	:		
DES	St	: :	2 2		*		**	;	lers,		:	:			,,	**	2	1	4		",	acke.	Brackets		:	en e		0 0	٠	10	-40	:0	61	(7)	64	-	1	ndles	*		Wheels,	Wheels,	Pulley Wheels,	Vhee	peels,	ü	:	1	1 2	Wheels				els, 5	era .	6	Whe	: '	z 1		els, 1			bs.	ivers	:	Bolts,	:		
	ated								Girc												"Itroubate	le Br	Bra			Pode,	TO TO	*	23	"	:	"	11	33	2	33	:	k Hand		als, 3"	V W	yed V	y WI	sed V	y W				MAThod	Mu				Wheels,	*	1	rate		5		Whe	DS	ners	g Cli	v Driv		and			-
	Perforated	2	2 2		*		**		Angle	:	: :	:	: :	2	*	ŗ	1			:	Elst 1	, -	Anole	0	,,	- 0	NAM	**	"	£	t,	33	33			:	:	Crank	:	Wheels,	Pulley	Flanged	Pulle	Flanged Wheels,	Pulle	"	"	33	Dark	Pinion				Gear		*	Contrate wheels		Devel		Gear Wheels,	Worms	Spanners	Spring Clips	Screw	ı	Nuts and	Nuts		Washare
	1 IA						-			_	-	-	-		-				- To	80 5	_			11-7		_				T	Total	-		les.											-					-			-			100													-	-

Jutfits-continued	
0	
of	
Contents	

	0 6	9 4	24 0	1 00	18	27	4 11	0 0	1 1	. ,	- t	- (	0 -	4 0	1 1	1	1	T	-15	_ ,	4 -	- F	10	63	14	2	9	13	73	4	9	_	4	œ	0 1	21	N	N C	4 0	4 0	0 0	9	10	ò«	4	OI O	) IC	io	x 0	100	- 4	9	41	4	2.	4 rc	9	1	4 00	01	ц,	- 01	н,	- 0	0 =	14	18
		1.1		1	1 1	1 .		_	1-	-	,	_		7 0	_ '	-1		-	- 2	1 0	0	F 1	-		_		**	4 1	-	1	4	1	_	_	_	01	~	,		٠ ٥	0 1		2		8	210	9 -	1	12	75.0	_ o	_	011			4 rc	9	10	4 rc	01	F .	- 67	-		112	-01	
- -		1 1	1					_	1			1		_	_				-	1	_		-	34	10	1		_	;		-			<u> </u>	_		-	1					-	_	_	-	9 8		_				805		_			_									
	21 23	9 4	01 0	1 4	14	1	0 4	4 0	1 12	•	4 [		4 0	4		1	_	-	-	_ (	0 -	4 -	'	29	4	2	61	6	23	8	61	9	61	2	4		1 '	71 0	4 -	1	9	16	30 8			'	4.4	4	x0 xx	001	α	,	21	CI	1	11	1		-	1	1.		1	1		4 27	
		ω .l	1	2	4	7	0	1 .	1 0	0	1 9	N C	N	L.		1	1	٦	l	1	4 -	٦.	1	10	2	2	-	33	2	3	-	io	61	7	27	1	1	- 0	4 -	1	9	10	4 ;	io –	7	19	N 00	41	- 4	121	-	1	٦	61	1	11	1	60	-	1	1	1	1	10	110	401	19
		ω 4	- 0	1 01	10	9	=	4 +		+ =	* "	6 0	7 7	4		1	ч	П	-	٠ ,	4	1	1	19	61	1	2	9	1	1	-	-	1	1	21	1	1	-			1	9	4	204	1	10	7 -	1	4	1	1	. 1	-	1	1		1	4	1	1		11	1	10	NO	1	8
1	11	01	- 0	4	1	1	0	٧.	٦ ,	4 =	4	0	N	1	1	1	1	1	-	1 -	-	1	1	6	I	1	64	Ī	1	1	1	_	I	1		1	1			1	1	61	Τ	П	1	Ī		1	1	1	-	1	- 1	1	1	11	1	27	1	I	1	1	1		-	1	١
1		20 01	ī	61	10	9	0	4	0	4	l u	0	10	4	1	1	-	1	1	٦, -	1	1	1	10	2	1	1	9	1	1	г	I	1	1	N	1	'	-		1	1	4	4	202	1	10	4 -	1	4	ī	9	1	П	1	1	H	1	7	1	1	ī	1	1	10	N -	- 1	C.
1	11		ī	1	T	4.	0	4	1			4	1	1	1	1	1	_	1	1		1	1	9	1	1	1	ıs.	1	ī	-	1	1	1 9	N	1	١.	-	- 1	1	-	61			1	0	4 -	ī	10	1	4	1	11	1	1	11	1	7		ī	i	I	ī	10	N -	1	-
1		7 7	<u> </u>	61	10	7	1	ı		4	1 0	0	0	,		i	-	1	1		-	1 1	-	4	2	1	I	1	1	i	-	1	1	i	1	1	1	1			1	63	4	11	1	1	11	1	. 2	1	10	ī	1 1	T	Ť	H	1	1	11	1	1	11	1	1	11	1.1	.6
1	<del>-</del> 1		1		2	77	1	1	1 -	-		0	1	1		1	1	1	1	_	1	1 1	1	4	1	1	1	1	1	<u>'</u>	-1	1	1	1	-	-	-	-				61	1	11	1	1	1 1	1		-	1	1	1	1	1	1 1	<u>.</u>	1	1	-	-	11	1	<u>.</u>	1 1	11	c
1	1		1	-	œ	-	1	1	1	_	1	1	1	-		1	_	1	1	1 .	_	1 1		1	2	- 1	1	-	-	1	1	1	-	1	1	-	1	1	1	_		-		1 1	1	-	1 1	1	1.6	_	1 0	1	-	1	1	1 1	+	-		1	1	1 1	-	1	1 1	1 1	
1	-1 -		-					1	1 "	-			1	_		1	-	-	-	-		1 1	-	- 1		-	1	1	-	+	1		-	<del> </del>	-		1	1				-	_	1 1		-	1 1	<u> </u>	1	_	1 -	·	1 1	-	-	1 1	-			-			1	-			
	1 1	- I	1	1	64	1						1	l .		-	-	1	1	1				- 1	-	- 64	-	1	1	1	1.	1	1	1			1	1			-	-	- 1	1	1 1	1	1		1	6	1	1 1	1	1 1	-	1	}	1	1	1	1	1		1				
	1-	11			9	l		1	1	-	1		1 '	N		-	-		1	1	-				1	1	1	I	1	1	-	1	1	1	1		1	1				-	4	11	1	1		1	11	1	10	1		1	1	11	1	1		1	1		1	l	1	1	
	1 1		1	_	4			l	1				1 °	4	- 1	J	1	1	1		1	1 1	1	1	1	1	1	1	1	-1	1	1.	1	1	1	1					1	1	I	11	1	1		-	11	1	10	1	11	1	1		1	1	1	1	1	11	1	1	11		
	-	1 1	1	1	7	1		1	-	4			1	1		Н	1	1	1	-	٦	1	-	1	1	1	1	1	1	1	1	1	1	1	1	1	1			1	1	1	4	11	1	1		1	1	1	11	1	11	1	1		1	1	1	1	1	11	1		11	1	
	1. 1	1-1	1		1	1	1		1			1	1	1		1	1	1	1			1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1			1	1	53	11	1	1	1	1	11	1		1		1	1	11	1	1	1	1	1	П	1		11	11	
	1	11	1	I	2	1		1	1 -	-		1	1	1	1	1	1	1		1 '	7		- 1	-	1	1	1	1	.1	-	1	1	1	١	١	١	1	1	i		1	1	61	11	1	Ī	11	1	11	1	1	1	11	I	1	11	1	I		1	1	11	1	1	11	1	
-	: :	: :	:	: :	:	:	:	:	T	:	:	:	:	:	:		:	:	:	:	:	:	:	:			:	:	:	:	:	:	i	:	;	:	:	:	:	: ,	:		:	:	: :	:	:	:	:	: :	:	: :	:	:	:		:	:	: :	:	:	: :	:	:	:	: :	:
	: :	: :	:	: :	:	:	:	:	:	1	:	:	:	:	Ė		:	;	:	:	:	:	: .	:			:	:	:	: :	:	:	:	:	:	÷	:	:	:	i	; .	: :	:	:	: :	÷	:	: :	;	: :	:	: :	:	: :	:	:	:	:	: :	:	į	: :	;	:	:	: :	:
	: :	: :	:	: :	÷	:	:	:	:		:		:	:	:		:	:	nals	:	;	:	:	:	:		:	:	:	:	;	:	:	:	:	:	:	:	:	:	:	: :	·:	:	: :	:	: :	:	:	:	:	: :	:	: :	:	: :	:	:	: :	:	:	: :	:	:	:	: :	:
	: :	: :	:	: :	:	:	:	;	: 0	104 104 104		N N	: ;	S	:		:	:	Mar	:	:	:	: -				:	:	:	:	:	:	:	÷	ŝ	:	:	: .	:	:	:	: :	:	:	: :	:	: :	:	:	: :	:	: ;	:	:	:	: :	:	:	: :	:	:	: :	:	:	:	: :	:
	1 :		× 13"	01 <b>ξ</b>	× (0)	(04 F	401 E	ins			::0	61	::	Flat	1	:	:	::	Sms	£3	:	:	: 0				:	:	:	÷	:	:	:	:	:	;	:	:	:	:	: ::			:	: :	:	: 1	:	:	: :	:	: :	:	: :	:	: :	:	:		:	:	: :	:	:	:	: :	:
	: :	21," ×	25° ×	11, × 12	×	×	× >	X	: -	riates, og	: .	Flates,	: :	1010	'n,				han	Farts	:	: ,	rino	0	:		:	:	:	:	:	;	:		:	:	:	:	i	1	rad	. 92	21, 23,	:	:.	;	:	: :	:	: :	:	: :	:	: :	:	: :	: :	:	: :	:	1	: :	1	:	:	: :	:
	: 8	só.		. 1	2	σ.	4 u	ñ		1 1 16	to the	I Fla	det	1 20	jon Folders	Manuals		1	Mec	ano	:		18.	rew			9	:	:	:	:	- (c)	23	25.		101 2		35	10 × 10	1, 1	10,	larg	22 848		14	3		, 31,	(01-(	N-pr	401-4	N		: :	;	: :		;	: :	:	s	: :	;	:	:	: :	
	Strij	trips Strir		3 3	,,	**			with boss	IISC.	Og X Cg	nge	45 × 25	nger.	Holy	Mar			lard	use Meccano	: =	0, 10	ve fo	St			rank	:	ys.	SS	:	×	23"×23	tes,		_	0	,	* C	4 -	51,	23,	25.	Chain .	,			8,3	7 6	6	- 10	Looms	rips	91,"	101	11	2,0	101	11,"	104	OOID			les.		37.00	
	ent.	nt S		: :			33			F.16	S, 03	113	4, 5	Fig	tion of				tand	se		2000 24 4	CTP	h S		Crar	H C	•	ling	Boss	rks.	8, 51	22	: Pla	٠,	spo	33	"	*	:	String		22	S S S		: :	£ :	Girders,	£	2 2	*	Ľ,	it Si		12					,	or L	lers.		Tal	es so	es, z	100
	S B	e Be e An							lece	alet.	late	alec	late	ater	thic		: :	*	no S	0	: :	3 5	ing 6	S wi		ded	e Ar	ings	Cour	ded	Fo.	Mate	*	gula	,	ed b					St	,		Ket				d Gi				s for	Girders		1	2	2 2	*	2		les f	Rol	".	ning	Ulat	Stri	3.11
	Springs Cranked Bent Strips	Double Bent Strips Double Angle Strips,	2	2 2	£	*	,,		Eye Pieces,	Ferrorated Flanged	riat Flates,	Periorated Flanged	Flat Flates,	Perforated Flanged Sector Plates	Of Instruction Folders	0	00-3	-7	Meccano Standard	How to	HOOKS	" (Loaded) Spring Cord, 40" length	Counting Screws for Spring Cord	Collars with Set Screws	Cranks	Threaded Cranks	Double Arm Cranks	Couplings	Strip Couplings	Threaded Bosses	Centre Forks	Flat Plates, 5½"×2½	"	Triangular Plates,		Screwed Rods,		2	2	2	Curved			Sproc	2 2		**	Braced		2 2	33	Teald	Single Bent S		: £	1	2 2	2	2 :		hutt	Wood Rollers	and	)esig	Face	Rack Strips, 34".	MACA

Contents of Outfits-continued

7	300044480480480480∞-∞-∞5α-∞44004×0001-00480000453480400
64	69ν   εεκο699   ε   ε   ε   ε   ε   ε   ε   ε   ε
9	ρ   σσσσσ   σ   44400   σ   ωσ44     4   σσ   σσσσ   σσσσσ
5.4	-   -
ıo	Φ   ΔHH           44 NO -   21               4         HHH   HH   HHH   HH   HHH   HHH   HHH   HHH   HHH   HHH
44	
4	Φ   αμμ           444   α
34	
93	©   auu
2A	
61	0 1 1
41	-
-	σ        ααα
0A	
0	Φ      ααα
00A	8
00	4
1	
RT.	Pins
PART.	Hinges  Hinges  Hinges  Hinges  Hub Discs (54½ diam.)  Chamel Segments (8 to circle)  Spring Buffers  Counpression Springs  Fran Couplings  Counpression Springs  Reversed Angle Brackets, 17  Fran Couplings  Counpression Springs  Reversed Angle Brackets, 17  Fran Couplings  Reversed Angle Brackets, 24  Corner Brackets  Rubber Rings, 34 diam.)  Boss Bell Cranks  Circular Sprices  Rubber Rings, 34  Circular Springs  Rubber Rings, 34  Circular Shrips, 34  Circular Saves  Contact Screws  6 BA. Nuts  Pendium Connection  Bubbins  Bubbins  1 Androw Cranke  2 Saves  Coli Checkes  1 Androw Cranke  1 Saves  Coli Checker  2 Saves  Coli Checker  2 Saves  Coli Checker  3 Saves  Coli Checker  3 Saves  Coli Checker  4 Saves  Coli Checker  5 Saves  Coli Checker  5 Saves  Coli Checker  6 Saves  6 Saves  Coli Checker  7 Pattom Scales  7 Pattom Scales  7 Pattom Scales  8 Saves  1 Saves  2 Saves  3 Saves
4 OF	n
DESCRIPTION	Hinges  Fork Pieces  Small Fork Pieces  Small Fork Pieces  Small Fork Pieces  Spring Buffers  Compression Springs  Framminns  Fight Tunnions  Spring Buffers  Compression Springs  Framminns  Fight Tunnions  Wheels, 2g' diam.)  Decoding Porchaetis  Wheels, 2g' diam.)  Decoding Porchaetis  Wheels, 2g' diam.  Dog Chutches  Circular Supports  Wheel Flanges  Circular Supports  Wheel Flanges  Circular Supports  Wheel Flanges  Circular Supports  Flandend Supports  Wheel Flanges  Circular Supports  Flandend Supports  Wheel Flanges  Circular Supports  Flandend Supports  Flandend Supports  Circular Supports  Wheel Flanges  Circular Supports  Flandend Supports  Washers  End  Buller Ends  Sowket Couplings  Flandend Supports  Flandend Supports  Circular Parckets, 2'x /1'x x granden  Flandend Supports  Washers  Flandend Supports  Circular Supports  Circular Supports  Washers  Flandend Supports
CRIP	Hinges
DES	Philips Phieses (Spirola phines) against the phines on Sprin phines on Sprin phines on Sprin phines (Spirola phines) and Spirola phines (Spiro
	Bolts #"  Hinges  For Piece Hinges  Channel Segment Spring Briffers of Channel Segment Spring Briffers of Channel Segment Spring Briffers  Trumions  Framinons  A proceed Angle J.  Framinons  Threedolite Prot Handers, 22  Corner Brackets, 23  Corner Strates  Threedolite Prot Handers, 24  Franch Lines  Threedolite Prot Handers, 24  Franch Lines  A proceed to Coupling  Franch Lines  A plant Ends  Circular Saws  Conflect Brackets, 34  Franch J.  Fran
	inges and the property of the
	Hinges  Threaded Pins  Threaded Pins  Fork Pleces  Threaded Pins  Fork Pleces  Hub Discs (34" (dam)  Spring Burlers  Compression Spring  Train Couplings  Train Couplings  Coupression Springs  Train Couplings  Threadell Protractors  Boos Bell Cranks  Boos Bell Cranks  Threadell Protractors  Handrall Supports  Wire Lines  Wheel Flanges  Wire Lines  Wheel Flanges  Wire Lines  Wheel Flanges  Threadell Protractors  Threadell Production  Wheel Flanges  Threadell Production  Wheel Flanges  Threadell Production  Wheel Flanges  Threadell Protractors  Wheel Flanges  Threadell Production  Wheel Flanges  Threadell Production  Threadell Carnel  Threadell Production  Threadell Production  Threadell Carnel  Threadell Production  Threadell Carnel  Threadell Production  Threadell Carnel  Threadell Production  Threadell Carnel  Threadell Carnel  Threadell Production  Threadell Carnel  Threadell Carnel  Threadell Threadell Threadell  Threadell Threadell  Threadell Threadell  Threadell Threadell  Th
	0 4 40 4 40 40 40
No.	1111 6 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1	

#### INDEX TO MODELS

Description.			Model No.
Acrobat , on See-sa	• • • •	• • •	2.15
		• • •	1.184
Aerial Flight	•••	••••	0.66; 1.218 0.99
" Ropeway	• • • •	***	00.60
Aerial, Cage " Direction			00.68
" Frame			00.80
Single Wi	re L		00.63
Domble W	ire I.		00.62
" Single Wi " Double W	re T		00 · 66
" Double W	ire T		00·67 0·119; 1·29;
Aeroplane	(	) · 20	0.119; 1.29;
	1 · 49 ;	1.17	8; 1·225; 2·48 00·100; 2·43
Airship , Mooring N	fact		$00 \cdot 100 ; 2 \cdot 43 \\ 00 \cdot 171$
			00-171
Angler			00·56; 0·105 0·15
Ape			0.33
Arc Lamp			00.163; 1.105
Arch			00·163; 1·105 0·123
Axe			$00 \cdot 127$
" Battle			00.58
" Fire		***	00.7
-			0.00
Baboon		***	0.83
Bacon Slicing Ma Bagatelle Table	cnine		0·52; 1·6 1·168
Y 11. 1	•••	•••	1.39
D	•••		0.50
Banjo Barge			00.78
Barrier, Level-Cro			00.173
Barrow			00.15
Coster's			0.69; 1.228
Battleship	• • •	0.23	3; 0.142; 1.206
	•••	• • •	(7(1 * 41)
Bellows Forge	• • •		1·78; 1·125 1·229
Belt Gear 1.5 Bench	. 1.1	4 . 1	1.229
Bench 1'3	; 1.1	4, 1	00.4 - 0.144
Bench Planing		:::	00.140
Bench, Planing Bicycle Billiard Player		***	0.46: 1.86
Billiard Player		***	0·46; 1·86 0·150
Birdcage and Sta	nd	•••	00.37
Blacksmith	•••		00·182; 1·128 1·131
Boat		• • •	1.131
" Ice		•••	3.13
" Motor		• • • •	00.22; 0.36
, Rowing	•••	• • •	00·22; 0·36 0·90; 1·70 00·148; 1·76
" Sailing " Torpedo	•••	• • • •	00.148; 1.76
Boat Steering Ge		•••	1.201
Book End			1 · 201 00 · 49
Bow and Arrow			1.46
		***	0.73
Box Ball Alley		***	1·46 0·73 1·154 1·166 1·3; 1·189 0·154
Boy on Swing Brake, Band		***	1 - 166
Brake, Band	• • •		1.3; 1.189
Bridge Double D	•••		0.154
High love	raw 1	• • • •	$1.109 \\ 2.10$
" High-leve " Railwa <b>y</b> v	with S	ional	2 · 55
Bucking Broncho		ignar.	0.32
Buffers			00.79
Butter Churn		100	0·32 00·79 1·139
Camera	•••		0.54
Candle Shade	•••	• • •	0.151
	•••	• • •	1.142
Cannon Puller	•••	• • • •	2·40 00·36
Candy Puller Cannon Car, Hand			00.159; 3.29
-un, andida			,

	TTA	v.	
Description.			Model No.
Car, Tandem Car Lifting App Carpenter's Squ			1.32
Car Lifting App	aratus		3.49
Carpenter's Squ	are	• • • •	00.12
Cart	•••	•••	00·143; 1 36 00·31
" Baggage	***	***	00.31
" Bullock " Hand	•••	•••	0.67
Duch	•••	•••	00·5 0·4
Theresia		•••	0.3
Catamaran			1.90
Catapult			00 · 181 ; 0 · 53
Cement Marker			00.21
Chaff Cutter		•••	0.8
Chair	111		1 - 59
" Arm			0.37; 0.102
" Baby	***		2.30
" Bath	00	0.164	; 0.148; 1.183
" Deck …	•••	•••	1.219
" Go	•••	•••	0.136
" Invalid	06	•••	$1.21 \\ 0.153$
" Revolving		•••	0.153
Chase, A Cheese Cutter	•••		00.73
CI I			0.16
Church			00.24
Clock			0.79
" Grandfat	her		00 · 149
Clothes Drying			00.121
" Hanger			00.8
" Horse			00.43
Coal Sifter		•••	2.19
" Cutter			1-122
Coaster	***	1.83	3; 1.110; 2.36
Coast Guard	• • •	•••	0.76
Coast Guard Coat Hanger	•••	(	00 · 135 ; 1 · 102
Coco-nut Sny	• • • •		1.179
Cot	•••	•••	0·26; 0·129 3·35
" Swinging	•••	• • •	
Cot on Wheels	•••	• • •	$1.58 \\ 0.130$
Cow and Milkm	oid	• • •	0.47
0			0.58
Decoled.			0.77
" Derrick			0.115
" Elevate			1.69
" "	Jib		1.203
" Grab			0.86
" Jib			0·6; 1·66 1·196
" Lorry			1.196
" Mobile			1.79
" Overhea	ad		1.158
" Patent	Luffing Travelli	•••	1·54 00·71
" Kadiai	ravelli Dreek	ng	
" Ranway	Break	lown	3·55 vel 3·45
" Revolvi	Wago	u Swr	00.61
	Ham	merhe	
" Rotatin	g		1.197
Swinalli	ng	0.13	5 : 1.60 : 1.165
" Swivem	Jib		1.156: 1.157
" Travelli	ng		1.85: 1.213
n n	Jib		5; 1.60; 1.165 1.156; 1.157 1.85; 1.213 2.16; 2.17 00.50
Crib			00.50
Crocodile			0.28
Crossbow	200	****	0·85; 3·16 del 1·126
Crosshead Demo			
Cum-bak		• • • •	1.48
Cutlery Basket	• • •	•••	00.189
" Rest	•••	•••	00.77
Dancer, The Me	ccano		1.123
- 411001, 1110 1110	June		

IVACAL				
Description.			Model N	0.
Dancers, Eccentr	ric		1.124	
Derrick	***	•••	2.45	
Desk Devil Wall Dignity and Imp	•••	•••	$00 \cdot 13$	
Devil Wall		•••	00 · 187	
Digitity and Imp	udenc	e	1.96	
Dinosaurus	***		0.91	
Disappearing Me		ian	1.95	0.4
Dividers	•••		00.3; 00	84
Dog Kennel	•••	•••	00·122 0·7	
" Kennel Drafting Machin		•••	3.8	
Drill	е	•••	1.53	
Automotio	•••	•••	1.103	
" Rock	•••	•••	0.131	
" Rock … Driller, Well	•••	•••	0·131 00·174	
Driller, Well Drilling Machine			125 ; 1 · 134	. 3.
Drinking Trough	•••		00 · 124	, 0
Drinking Trough Drop the Nigger	loste.		3.51	
Dump Car			0.116	
Easel			2.37	
Easel Eiffel Tower		•••	1.104	
Electric Loco			0.94	
Elevator	***	1.98	; 1·222; 00·88	2-1
Elevator " Car		•••	00.88	
			1.80	
Embossing Mach	ine	•••	2.54	
Emery Wheel		•••	1.210	
Engine, Beam		•••	1.74	
" Horizon	tal	0.14	6; 3.17;	3.2
" Iwo-cyl	inder	vertica	3.30	
Emery Wheel Engine, Beam "Horizon "Two-cyl "Vertical Execution, The	Steam	n	0.50	
Execution, The Extended Ash Ti	 ip		0·56 1·164	
Extended Ash 1	ıp	•••	1.104	
Fan			0.75	
Coiling			00.142	
Farm Sight	•••		00.18	
Fencers, The			0 107	
Fire Alarm , Engine, M , Escape Flax Cleaner Flex Making Mac	•••		1.217	
Engine, M	lanual		1.107	
" Escape		00-11	5; 2.12;	3.2
" Escape Flax Cleaner Flex Making Mac Flip-Flap		•••	3.44	
Flex Making Ma	chine	•••		
Flip-Flap			1.77	
Flip-Flap Flower Pot Stan	d	•••	00 · 175	
FIV Boats			0·93; 1·1 1·177	182
Flying Boats	•••		1.177	
Machine		•••	1.150	
Footbridge	***	•••	0.84	
Foot Hammer Fork	***	***	1·115 00·128	
Fork Friction Grip To	nge	•••	00.44; 1	47
Frog			0.81	41
1106		•••	0 01	
Gallows			00.168	
Galvanometer			0.68	
Gangway			0.34; 1.	50
Gangway Garden Roller			00 - 170	
	el		00 · 190	
Gate	•••	(	00·38; 1· 3·15	151
Gauge, Railway		•••	3.15	
" Track	•••		00.34	
Girder, Bow		• • • •	1.214	
Glider	•••	•••	00·117 2·2	
Gondola			1.900 . 0	. 0
Girder, Bow Glider Gondola		•••	1.209; 2	-0
Gondola Gong Goose Governor Centr	ifugal	Engine	0.63 - 1	.67
Goose Governor, Centr " Inver Gramophone	ted Ce	ntrifue	al 1.140	o,
Gramophone			0.40; 1.	195

Description.			Model No.
Cross Cuttor			
Grass Cutter		•••	0.89
Grass Cutter Gradient Indicate	rs	00	·107 to 00 · 114
Crearel Cifter			00.57
Gravel Sifter			
Gravity Conveyor			1.118
C III			00 105
Grill Grinder, Coffee Knife Guillotine Gun, Anti-Aircraf			$00 \cdot 137$
Grinder Coffee			3.39
Gillider, Collec	***		
Knife			3.33
C-ill . Air -			
Gumotine			1.99
Cun Anti Airoraf	+ 1	00.158	; 1.145; 2.47
Gun, Anti-Anciai		00.199	; 1.149; 2.4/
" Big " Field, and C			00.180
" F: 11 . 10		•••	00 200
" Field, and C	arriag	e	0.31
" Lewis " Machine			00.28
" Lewis	***	***	00.20
Machine		***	0.108
" Machine	***		0.100
" Machine " Old Siege " Quick Firing			0·108 0·140 1·161
" Out als Eining	_		1 101
" Quick Firing	5		1.101
Gymnast			0·24; 1·88 1·227
Gymnast	***	***	0.24, 1.00
" Revolvin	g	***	1.227
C	0		1 000
Gyroscope			1.202
22 S 85 C 63			
Hack Saw, Power Hammer, Double			0.139
Hammer	Dec		
Hammer, Double	Drop		2 · 1
	-		1.91
		***	1.91
Machan	ical		1 - 33 - 2 - 22
			1 00, 100
" Trip	***	***	1·33; 2·22 00·166
Hammock			0.134
Hand Dunch			3.43
riand runch			
Hatchet Hat Rack Hay Tedder			$1 \cdot 24$
II ( D 1			0 100
Hat Kack			0.120
Hay Todder			2.9
riay reduct			
Hen			0.88
Hen "H" Girder			
H Girder	***		1.4
High lovel Dridge			2.10
High-level Bridge			2.10
			00 .139
	***		
Hoisting Block Hooke's Coupling			1.89
The leade Counting			
Hooke's Coupling		***	1.188
Horse			$00 \cdot 130$
110150			
Horse  " and Cart " Prancing " Toy	1502		1.52
" D			0 100
Prancing			0.133
" Toy			00.104
" 10y			$00 \cdot 104$
Horseman			1.75
Tiorseman			1 70
Horseman's Fall		***	0.74
Y Y			
Howitzer	***	***	1.82
Hurdler			0.60
Inclined Plane Invalid, The			1.120
Y 1: 1 TT			1 07
invalid, the			1.37
			1.152
mverted muss	***		1.102
Y 1 TO 11			
Jockey Pulley			1.1
			00.178
July Wheel		***	
			00.64
2 Paris Jack	•••		
Key, Double Cab	0		1.130
		•••	1 100
Kinetograph			3.57
17: 3/			1 010
Kinetograph King Meccano			$1 \cdot 212$
Lace Jennier			3.9
Laddon			00.10
Ladder	***	***	00.10
on Wheels	00.	185. 1.	42.1.148.2.30
" On wheels	, 00	.50, 1	00·10 ·42; 1·148; 2·39 00·47; 3·7 1·200
Step			00.47: 3.7
Ladle Ciant F	nde-		1.000
Ladle, Giant Four Lamp Standard	udry		1.200
Lamp Standard			1.193
	•••		1.190
Lancer			1.197
Latha			1.111 . 9 40
Lathe " Bench " Treadle		(	0·111; 3·48 0·143
Bench			0.143
" Belich			0.140
lreadle			2.6
Lawn Marker			3.28
Lawn Marker		***	0.28
Mower			1.31 . 3.34
T " TE			0 00 1 100
Lazy Tongs			0.22; 1.199
" Mower Lazy Tongs Letter Balance Level Crossing Ba		0.177	1.22 . 2.2
Letter Dalance	0	0.111	, 1.22, 0.0
Level Crossing Ba	rrier		00 · 173
Drowning De			

### INDEX TO MODELS (continued)

				4
	Description.			Model No.
		st Orde	r	00 4 5 4
	" " Se	cond		1.7
	" " Th	ird "		1.8
	Light Cruiser	"		0.9
	Liner			00.55
	Locomotive			1.170 : 1.207
	Loom, Hand			1.92
	Lorry, Motor		1.94	00·154 1·7 1·8 0·9 00·55 1·170; 1·207 1·92 1; 1·204; 2·24 2·20 3·38 0·45
	Steam	***		2.20
	Tank		555	3.38
	Loud Speaker			0.45
1	Luggage Cart			1.221
•	-ussus Care	***		
	Machine for trac	ing a lo	ocus	1.143
Ì	Machine for tra- Magic Plate Mail Bag Hange Man and Boy , Climbing I Master and Stur Mat Frame Meccangaroo Meccano Boy , Man Mechanical Gon Medal			00.74
]	Mail Bag Hange	r		00.59; 00.92
J	Man and Boy	***		1.144
	" Climbing I	ole		1.64
]	Master and Stud	lent		1.84
1	Mat Frame	***		2-28
4 7	Meccanyaroo			3.24
î	Meccano Boy	•••		0.48
	Man	***		00.33
•	Macconograph			1.146
1	Mechanical C			1.174
	меспапісаі бол	S		0.12
1	Medal Milk Maid Missing Link, T Monoplane Meno Rail Motor Car " Raci " Cycle and " Cyclist and Mountain Trans	• • • •		0.13
1	Milk Maid		***	0.41
1	Missing Link, T	ne		0.70
1	Monoplane			$2 \cdot 25$
1	Meno Rail			$00 \cdot 147$
]	Motor Car			00 • 125 ; 1 • 137
	" " Raci	ng		1.135
	Cycle and	Sideca	ır	0.44
	Cyclist at	nd Pillio	on Rie	ler 1.112
1	Mountain Trans	port		1.44
í	Mounted Comb	Porc	•••	1.81
	Mountain Trans Mounted Cowbo Music Stand			0.122
	Newton's Disc Notice Board			
	Newton's Disc			3.46
	Notice Board	•••		0.121
	Oil Cake Chopp	er	:::	3.12
				00.176
	Ore Crusher			00 170
-	Ore Crusher Organ			$00 \cdot 123$
-	Ore Crusher Organ Ostrich			00 · 123 00 · 48
				00·123 00·48
				00·123 00·48
				00·123 00·48
	Pantograph Parallel Bars Pastry Designe	 r		00·123 00·48 1·192 0·149 3·50
	Pantograph Parallel Bars Pastry Designe	 r		00·123 00·48 1·192 0·149 3·50
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1	 r 52; 0·:	  11; 0	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me	52; 0·1	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me	52; 0·1	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver	52; 0·2	  11; 0·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 60-1 Performing Me Piano Pile Driver Pistol Piston Connect Pithead Gear Planing Bench Plasterer's Har	52; 0:: ccanitia  ion, Dou 00:14	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00-1 Performing Me Piano Pile Driver Pistol Piston Connect Pithead Gear Planing Bench Plasterer's Har	52; 0:: ccanitia  ion, Dou 00:14	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00-1 Performing Me Piano Pile Driver Pistol Piston Connect Pithead Gear Planing Bench Plasterer's Har Plers Plough Prographic Grap	52; 0 · · · · · · · · · · · · · · · · · ·	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Pleough Pneumatic Gra Paolishing Sping Sping	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 ·13; 2·14; 3·37 00·140 00·23 0·62 0·6; 0·118 0·82 0·82 2·63
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Pneumatic Gra Pneumatic Gra Pachishing Spin	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 ·13; 2·14; 3·37 00·140 00·23 0·62 0·6; 0·118 0·82 0·82 2·63
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Pneumatic Gra Pneumatic Gra Pachishing Spin	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62 0·62 0·62 0·82
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Pneumatic Gra Pneumatic Gra Pachishing Spin	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62 0·62 0·62 0·82
	Pen Rack 00-1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Plough Pneumatic Gen	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62 0·62 0·62 0·82
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Pneumatic Gra Pneumatic Gra Pachishing Spin	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·23 0·62 0·62 0·62 0·82
	Pantograph Parallel Bars Pastry Designe Pecking Hen Pen Rack 00·1 Performing Me Piano Pile Driver Pistol Connect Pithead Gear Planing Bench Plasterer's Hav Pliers Phough Pneumatic Graph	52; 0.: 52; 0.: ccanitia  ion, Dou 00.14 vk in Elev	11; 0 · · · · · · · · · · · · · · · · · ·	00·123 00·48 1·192 0·149 3·50 0·59 72; 0·96; 1·106 2·29 0·39 1·114; 3·19 0·57 ction 1·41 13; 2·14; 3·37 00·140 00·62 00·6; 0·118 0·82

111	ĮD.	CA	10	IV
Description. Press, Automatic Print Trimmer Propeller Pulley Block Sharting Pullman Car Pump Double Act Windmill		M	lodel No.	1
Press, Automatic	Dial	***	3.10	
Print Trimmer			00.75	
Propeller			00.89	10
Pulley Block	0:114	; 1.16;	1:17; 1:	18
" Sharring	le Sue	ave o.	133 : 00 : 12	56
Pullman Car		00	00.179	00
Pump			0.98	+
" Double Act	tion		$1 \cdot 215$	T
" Windmill			1.138	
Punching Bag Sta	and		0 · 137	
Punching Bag Sta Machin	е	0.	1 · 215 1 · 138 0 · 137 147; 1 162	
	***	0.000		
Quick Delivery C	bute	•••	1.173	
Return De	vice	*** . DIE	1.169	-16
54.11(0)	. 5.5	ngi		124
Quick Delivery Construction Return De		33	1 · 141 00 · 72 3 · 45 00 · 45 ; 1 · 1	736.5
" Signal, I	rench		00.72	25-36
" Wagon S	Swivel	Crane	3.45	66
Kake	'	00.54; (	00 · 45 ; 1 · 1 · 5 ; 1 · 117 1 · 63	100
" Tiorse		0	1.63	120 E
Rake Horse Large Rat Trap Rattle Razor	411	0	1.190	24.5
Rattle		0 -	103; 3.31	
Razor			00·90 00·51 0·92 00·17	
Refreshment Wa	gon		00.51	7
Rickshaw			0.92	Ban
Rine with Bayon	et		.94 - 00 - 9	9
Rocking Horse	7	177	0.25	,
Roller, Field		00	.70; 1.97	
Razor Refreshment Wa Rickshaw Rifle with Bayon Road Sign Rocking Horse Roller, Field "Furrow" Steam Ro Roman Balance Roulette Wheel Roundalout 0			.00 · 138	100
" Steam Ro	oad		3.32	10.5
Roman Balance	• • •	***	00 - 136	187
Roundabout 0	0.153	1 211	2.51 . 3	-52
Roundabout	0.100	1 211	2 01, 0	02
			31	3215
Safety Catch for Sand Yacht Saw, Band "Circular "Meat Mechanical	Wind	ing Gear	1.62	DEC.
Sand Yacht		00	184 - 1 - 16	30
Sand Facilit Saw, Band "Circular "Meat "Mechanical		00	151 : 1-17	1
" Meat			00.2	1
" Mechanical				
" Two-hand			00 134	617
Sawing Horse			00·155 1·185	
" Machine Saxophone			0.29	
Scales 00·41	. 00.	120: 0:	126: 0.13	27 :
1.116	1.16	33 ; 2.32	0·29 ·126; 0·15 2; 3·6; 3 3·4	.27
Scarifier Schooner, Square			3.4	
Schooner, Square	Tops	ail :	2.31	00
Scooter		0.1;	2·31 0·55; 1 00·39 2·5	.38
Scrap Reel Seaplane, Schnei	dor Tr	conhy	2.5	7
Searchlight	der 11		00.126	
Seat, Garden			.00 · 46	2.
" Umpire's		10.1	1.180	2.52
Sedan Chair			1.176	. 1
See-Saw		0.	124; 1·22 ·100; 3·20 1·186	4
" Danielini	ng	1	1.196	,
" Revolvi	bout		2.3	Piles
Seismograph			2·3 1·65	157
Semaphore			00 - 101	f.com
Set-Square, 45°			1.12	
, 60°			1 13	- 1
Sewing Machine			2:46	
"Rounda Seismograph Semaphore Set-Square, 45° 60° Sewing Machine Shade, Candle Shearing Machin		•••	0.104	
Production and contract		***		

Description.	Model No.
Shepherd's Crook	1.121
Dirip 3 Dainip	00 10
Shovel Mechanical	1 · 205
Steam	1 · 57
Sifter	2.38
Signal	1.149
Eronoh Poilagou	1.51
" Junction	0 · 141
oigh Tost, One-way	00.97
" two-way	00 · 81
,, three-way four-way	00.91
Single Sheave Pulley Bl Ski-Runner	lock 0·109; 0·128
Ski-Runner	00 · 186
Sled 00 Sleigh, Horse Smoothing Iron	0.11; 00.188; 0.138
Smoothing Iron	2.4
	0.70
Spade	00 · 20
Spindle, Buffing Spinning Buttons Stamp, Drop	00 · 183
Spinning Buttons	1 · 61 1 · 127
, Mechanical	1.127
Stamping Machine	1 · 198
Mill	00.118 2.49
Steam Engine, Vertical Road Roller	3 · 47
Steamer, Paddle	1 · 147 ; 3 · 56
Steamer, Paddle Steeple Chaser	1 · 147 ; 3 · 56 0 · 71
Stone Sawing Machine	1.68
Stool	00.146
" Piano Street Lamp	00 · 103 - 00 · 95
Strip Bending Machine	3.2
Strong Man	0.19
Submarine	0 · 17 ; 1 · 181
Sudden Appearance, A	1.108
Sulkey Swing	00.69: 0.117: 3.11
Boat	00.69; 0.117; 3.11
Automotio	3.26
Switch	00.29
Switchback Sword	00.105; 0.42
Sword	
Table	00·1; 00·53; 0·27 00·169; 1·119
, Dea	
" Collapsible	00 · 25
" Drafting Tappet Valve Demonst	
	1.111
Telegraph Kev	00 · 76
,,	
Telescope Telescopic Mast	1.175
Telpher Span	0 · 49 ; 1 · 93 1 · 43
Telpher Span Tennis Player Three Wheel Auto	
Three Wheel Auto	0 · 12
THE PERIOD PROPERTY	0·12 0·10
Ticca Gharry	0.12 $0.10$ $1.23$
Tight Rope Walker	0·12 0·10 1·23 1·40
Tight Rope Walker Timber Drag	0·12 0·10 1·23 1·40
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon	$\begin{array}{cccc} \dots & 0 \cdot 12 \\ 0 \cdot 10 \\ \dots & 1 \cdot 23 \\ \dots & 1 \cdot 40 \\ \dots & 1 \cdot 30 \ ; \ 1 \cdot 159 \\ \dots & 00 \cdot 82 \\ \dots & 2 \cdot 52 \\ \end{array}$
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon Toast Rack	0·12 0·10 1·23 1·40 1·30; 1·159 00·82 2·52 1·191
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon Toast Rack Toboggan	0·12 0·10 1·23 1·40 1·30; 1·159 00·82 2·52 1·191 3·14 1·35
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon Toast Rack Toboggan Top	0·12 0·10 1·23 1·40 1·30; 1·159 00·82 2·52 1·191 3·14 1·35
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon Toast Rack Toboggan Top Top Spinning	0·12 0·10 1·23 1·40 1·30; 1·159 00·82 2·52 1·191 3·14 1·35
Tight Rope Walker Timber Drag Tin Opener Tipping Motor Wagon Toast Rack Toboggan	0·12 0·10 1·23 1·40 1·30; 1·159 00·82 1·91 1·191 1·35 00·26; 2 <sup>2</sup> 7

Description.			Model No. 1.136; 1.167 0.35
Tractor, Motor	•••	1	1.136; 1.167
Tramway Car Tramcar, Electric Treadle Grindston			0.35
Tramcar, Electric		•••	$3.5 \\ 1.172$
Triangle of Force	ie.	• • • •	1.172
	••••		0.61 - 2.23
Carrier			0·61; 2·23 2·41
Tricyclist, Revolv	ing		1.55
Trip Hammer			00·166 00·102
Tripod			00.102
Lland	) · 27		7; 0·30; 0·95 3·22
", Porter's			00.86
Trowel			00 · 14
" Mason's			00.30
Truck			1.56
" Baggage	• • •	***	00.96
" Bogie	• • •	2.55	00.129
" Cattle		***	0·21 2·18
Fire			3.41
" Flat			00-19
" Hand		0	0.93; 00.172
" Lumber		0	0.131 ; 00.144
" Luggage		0.2;	0.93; 00.172 0.131; 00.144 0.100; 1.87 1.226; 2.33
" Motor	• • • •		1·226; 2·33 2·7
" Revolving " Timber		***	00.54
with Sides	•••	555	1.25
Truss, Compound	l Tri		
			1 · 10
" Howe " Triangulat	ed		1.11
Try-your-strengt	h Ma		1·129; 2·50 00·35; 2·21
Turnstile Turntable	•••		00.35; 2.21
Turntable Tweezers	•••	• • • • • • • • • • • • • • • • • • • •	00.83
I WOODELD III			
Umbrella Stand			00.106
Van, Motor			1.132; 2.44
Velocipede			00.9
Viaduct			0.113
Violin			00·42 1·73
" and Bow			1-73
Wagon, Dinner		(	00.141; 1.27
Steam			3.58
Tank			3.21
lea		(	00.165; 0.110
., Timber	•••	·	00.65
" Tip			1.28
,, Tower	1-4		4; 1·216; 3·18 0·97
Walking Man " Stick	•••		00.87
Watch and Chai	n		00 · 119
Stand			00 - 150
Weather Vane			0.112; 1.72
Well Driller ,, Windlass	• • • •		00 · 174
,, Windlass	•••		0·112; 1·72 00·174 0·132 1·34
Windlass			1.113
" Chines Well			0.132
Windmill		00-167	; 0.80; 2.42
Wire Rope Make	er		1 · 101
Wiretail			0.51
Wrestlers	•••		0.64; 1.71
57. 14			00.00
Yacht	•••		00 · 98 00 · 160
" Ice " Land			3.40
" Land			T

#### Patents and Designs Great Britain

250,378 671,485 253,236 671,534 290,121 671,790 648,958 680,416 671,484 682,208

## MECCANO

#### THE TOY THAT MADE ENGINEERING FAMOUS

Millions of boys in every country throughout the world play with Meccano.

These are the Meccano Factories and distributing centres.

Patents and Designs Great Britain

682,209 718,404 682,934 718,731 683,011 733,541 686,112 733,542 698,054 740,413

London Office and Warehouse:

Meccano Ltd.,

Walnut Tree Walk,

Kennington Road, London, S.E.11.




London Service and Repair Depot:

Meccano Ltd.,

5/6, Marshall Street,

London, W.I.



Head Office and Factory: OLD SWAN, LIVERPOOL.

#### Meccano Agencies:

Alexandria, Algiers, Amsterdam, Auckland, Barcelona, Basle, Bogota, Bombay, Brussels,
Buenos Aires,
Cairo,
Calcutta,
Cape Town,
Caracas,
Constantinople,
Durban,

Genoa, Hong Kong, Iquitos, Johannesburg, Karachi, Mexico City, Monte Video, Oslo, Para, Rio de Janeiro, Santiago, Sao Paulo, Stockholm, Sydney, Tampico, Tanga. Hornby-Meccano G.m.b.H., Alte Jakobstrasse 20-22 (Bergmannshof), Berlin SW.68.

Canadian Office and Warehouse:

Meccano Ltd.,

34, St. Patrick Street, Toronto.



Meccano (France) Ltd., 78-80, Rue Rébeval, Paris XIXeme.